Reconsideration of Case Histories for Estimating Undrained Shear Strength in Sandy Soils

C.E. (Fear) Wride¹, E.C. McRoberts² and P.K. Robertson³

Corresponding Author:

Dr. C.E. Wride 220 Civil/Electrical Engineering Building University of Alberta Edmonton, Alberta CANADA, T6G 2G7

> Phone: (403) 492-9646 Fax: (403) 492-8198 e-mail: <u>cewride@civil.ualberta.ca</u>

May 6, 1998 Submitted to the Canadian Geotechnical Journal

¹ Post-Doctoral Fellow, Geotechnical Group, Department of Civil and Environmental Engineering, University of Alberta, Edmonton, Alberta, Canada.

² Chief Technical Officer, AGRA Earth and Environmental Ltd., Edmonton, Alberta, Canada.

³ Professor, Geotechnical Group, Department of Civil and Environmental Engineering, University of Alberta, Edmonton, Alberta, Canada.

Reconsideration of Case Histories for Estimating Undrained Shear Strength in Sandy Soils

C.E. (Fear) Wride, E.C. McRoberts and P.K. Robertson

Abstract

When sandy soils respond in a strain-softening manner to undrained loading, an estimation of the resulting undrained shear strength (S_u) is required to determine the potential for flow liquefaction at a given site. One of the most commonly used methods for estimating the undrained strength of liquefied sand is an empirical SPT-based chart (originally proposed by H.B. Seed), which was developed using a number of case histories. The original interpretations of these case histories are viewed by many workers and regulatory agencies as the most authoritative measure of the liquefied strength of sand. Consequently, in comparison, other less conservative methods are generally held in an unfavourable light. This paper re-examines the original database of case histories in view of some more recent concepts regarding soil liquefaction. The objectives of this paper are to explore and re-assess the issues involved in the original assessment and to offer alternative views of the case records. The conclusions presented here indicate that alternative explanations of the liquefied strength of sand are not inconsistent with the original case histories.

Key words: sandy soils, soil liquefaction, undrained strength, SPT

Introduction

If a sand is considered to be strain-softening (i.e. susceptible to flow liquefaction), an estimation of the resulting undrained shear strength (S_u) is required for stability analyses for either statically or dynamically triggered flow liquefaction. One of the most commonly used methods for estimating the undrained strength of liquefied sand is the SPT-based chart by Seed and Harder (1990), based on earlier work by Seed (1987). The chart is based on 17 case histories and provides a relationship between S_u and equivalent normalized Standard Penetration Test (SPT) resistance, (N_1)₆₀, in clean sand. Figure 1 presents a metric version of the Seed and Harder (1990) chart, identifying the case histories by number. Table 1 summarizes the data presented in Figure 1, in tabular form.

Several issues arise in practice when using this relationship, which is considered by many to be the most authoritative standard for assessing the undrained strength of liquefied soil. First, there are other techniques available for assessing the undrained strength of loose sand (e.g. Byrne et al., 1994; Fear and Robertson, 1995; Konrad and Watts, 1995; Yoshimine et al., 1998) which often result in higher design strengths for denser soils than those predicted by Figure 1. Second, practice often results in a lower bound assessment of the lowest $(N_1)_{60}$ for a given site or soil unit and the subsequent introduction of this value into the lower bound relationship given in Figure 1. As will be shown, the selection of the $(N_1)_{60}$ values in the original interpretation of the case histories often did not adopt a lower bound of the in-situ $(N_1)_{60}$. Therefore, a considerable degree of potentially unwarranted conservatism can be introduced when Figure 1 is applied in practice. Thirdly, Fear and McRoberts (1995) reviewed the database compiled by Seed et al. (1984) and presented an alternative assessment of the seismic triggering of sands using a lower bound

assessment of the site data. The conclusion was that triggering was not observed above an $(N_1)_{60}$ of about 15. Therefore, it can be suggested that the prediction offered by Figure 1 (i.e. that a sand with $(N_1)_{60} > 15$ may have a strain-softening response and a low undrained shear strength) may well be unlikely. Finally, it is possible that some of the case histories are cases of true flow liquefaction for which S_u is meaningful; however, some of the case histories appear to be cases of cyclic liquefaction for which deformations might be associated with a loss in soil stiffness rather than a loss in soil strength (Robertson, 1994).

The intent of this paper is to provide a review of the original case records in order to consider if an alternative view – and one more supportive of other developments in liquefaction – could be seen in the original database. The review of the database presented in this paper assesses the case histories on a somewhat qualitative basis. A full discussion of the database is provided in one chapter of the first author's Ph.D. dissertation (Fear, 1996). Further studies into each of the individual case histories would be both interesting and useful in an attempt to answer some of the questions that are raised here and to assess the case histories in a more quantitative manner.

Historical Information about the Case Histories

Essential statistics

Table 2 summarizes some essential statistics for each of the individual case histories. Included in Table 2 are the 17 case histories from the original database by Seed and Harder (1990), three case histories added to the database by Stark and Mesri (1992) and an additional case history, Duncan Dam (Byrne et al., 1994). The case histories are identified by name and number. The numbers were used to identify the case histories in Figure 1 and are used in subsequent figures throughout

this paper. Included in Table 2 for each case history are the initial height and slope angle, the type of trigger mechanism, the earthquake (EQ) magnitude and acceleration (if applicable), the nature of the observed failure, the runout distance (defined as the horizontal distance from the toe of the original slope to the toe of the post-failure slope) and the post-failure slope angle.

Other key facts

Detailed descriptions of each of the case histories are provided by Fear (1996), based on the work by Seed (1987), Seed and Harder (1990) and Stark and Mesri (1992) as well as the many original references for each case history. Thus, these descriptions will not be repeated here. However, several key facts will be emphasized, as outlined in Table 3 and described below. References for each case history in addition to the three main papers are cited in Table 3.

As indicated in Table 3, the various failures occurred between 1918 and 1987. Nine of the failures occurred prior to 1970. It is likely that the data for older case histories may be less reliable than those for more recent failures. A related fact is that there were no SPT data available for most of the failures which occurred prior to 1970; only limited data were available for the Fort Peck Dam case history. For two of the later case histories, only Becker penetration test (BPT) data or cone penetration test (CPT) data were available. In the case of the Lower San Fernando Dam, only post-earthquake downstream SPT data were available; using various assumptions, these data were extrapolated to pre-earthquake upstream SPT data. Therefore, for many case histories, values of $(N_1)_{60}$ can only be estimated and, as a result, are less reliable. In addition, as indicated in Table 3, both the Lower and Upper San Fernando Dams consisted of highly stratified deposits. In such materials, selecting a representative $(N_1)_{60}$ is very difficult.

For each case history, Table 3 also indicates the type of structure involved, the direction of the failure, whether the failure involved a mass of soil or a distinct layer of soil, and various other observations regarding the nature of some of the failures, as reported in the literature. Consequently, the table is useful for identifying some additional similarities and differences between the various case histories.

The additional case history presented here is Duncan Dam. Duncan Dam is a hydroelectric dam located on the Duncan River, about 8 km upstream from Kootenay Lake in southeastern British Columbia, Canada. The dam itself has never experienced a liquefaction failure; however, a recent dam safety review by B.C. Hydro (Little et al., 1994) investigated the seismic resistance of the dam, with liquefaction resistance of primary concern. Duncan Dam is a zoned earthfill embankment founded on sandy soils. In-situ testing and sampling (Sego et al., 1994; Plewes et al., 1994), laboratory testing of undisturbed frozen samples (Pillai and Stewart, 1994) and subsequent analysis (Pillai and Salgado, 1994) indicated that the soil unit of greatest concern was Unit 3-c, which is located under the downstream side of the right half of Duncan Dam. Unit 3-c consists of uniform fine sand with approximately 5% fines. The sand is composed of angular to subangular grains of quartz, plagioclase, K-feldspar and calcite-dolomite.

Representative values of $(N_1)_{60}$ and S_u selected by other authors

Over the years, different researchers have assigned different representative values of $(N_1)_{60}$ and S_u to each case history in the Seed and Harder (1990) and Stark and Mesri (1992) databases. These values are summarized in Table 4 and Table 5, together with comments as to how they

were selected by the various authors.

At Duncan Dam, the in-situ site investigation found that the SPT $(N_1)_{60}$ increased non-linearly with increasing overburden stress (Byrne et al., 1994; see Table 6). Laboratory testing (post-cyclic undrained monotonic simple shear tests) of undisturbed frozen samples concluded that an undrained residual shear strength ratio, S_u/σ'_{vo} , of 0.21 was applicable to the Unit 3-c sand (Pillai and Salgado, 1994). As shown in Table 6, the site investigation and laboratory testing results for Duncan Dam can be combined, in order to correlate values of S_u with values of $(N_1)_{60}$ for given values of overburden pressure. These datapoints can be plotted and compared with the other empirical case histories discussed above, keeping in mind that this case history did not fail.

Classification of the Case Histories

Summary of case history statistics

As mentioned earlier, Table 2 summarizes essential details for each of the individual case histories. Based on the details in Table 2 and the information presented earlier, the case histories in Table 2 have been classified into various categories in an attempt to ultimately distinguish between cases of flow liquefaction (strain-softening response) and cyclic liquefaction. Of the 21 case histories listed in Table 2, three case histories were statically triggered failures, while 17 case histories suffered some type of deformations as a result of cyclic loading. The cyclic loading was predominantly earthquake loading, but one case history (18, Lake Ackerman) was triggered by cyclic loading related to a seismic exploration. The type of failure assigned to each case history in Table 2 will be discussed below.

Comparison of initial conditions

Table 2 clearly indicates that the database contains a wide range of initial slope height and angle combinations. Five case histories had initial slope angles less than 5° (this includes case history 6, which was not a slope, but a building on level ground). Of these five case histories, only case history 10 (San Fernando Juvenile Hall) has a large slope height (i.e. > 10 m). As explained in Table 2, this is a result of the fact that the lateral spread at the site was approximately 1.2 km long and thus there was a 30 m height difference between the toe and head of the slide mass area. Eight case histories had initial slope angles greater than 25°, but all of these case histories had initial slope heights of less than 11 m. Nine case records had initial slope angles ranging from approximately 11° to 22°. Although one of these case records (2, Sheffield Dam) had an initial slope height of 7.6 m, the others had much higher initial slope heights ranging from 17.6 to 61 m.

Comparison of observed deformations

Drawing on the information in Table 1 and Table 2, Table 7 provides a summary of the simple deformation analysis performed as part of this study. For each of the case histories, several terms have been computed to help quantify the observed deformations relative to those experienced by the other case histories in the database.

The observed runouts for the various case histories cannot be compared directly because of the wide range in initial slope height (see Table 2). It is logical to conclude that as the initial slope height increases, observed runouts could increase as a result of the higher driving stresses and the additional momentum that the material will gather as it fails. Dividing the observed runout by

the initial slope height provides a simple way of comparing relative runouts between various case histories. Table 7 indicates that nine of the case histories had relative runouts of 3 or greater. The remaining case histories had relative runouts ranging from zero to 2. A related term to the relative runout ratio is the amount of horizontal strain that occurred. This was defined by simply dividing the observed runout by the initial slope length (defined as the horizontal distance from the toe of the initial slope to the point immediately below the crest of the initial slope) and expressing the result in percent. Table 7 indicates that eleven of the case histories had horizontal strains greater than 90%. Four of the case histories had horizontal strains less than 4%.

Another simple measure for comparing the deformations of the various case histories is the relative slope ratio. This is defined as the ratio of the post-failure slope angle to the initial slope angle. Table 7 indicates that four of the case histories had relative slope ratios of 1.0; i.e. no significant change in slope was observed from before to after the soil failure. Ten case histories had relative slope ratios of less than 0.40. Figure 2 indicates that there is a clear relationship between relative runout and relative slope angle for all of the case histories. This is to be expected because a slope that runs out further relative to its initial height would obviously have a lower ratio of its post-failure slope angle to its initial slope angle. However, as will be discussed further in later sections of this paper, what is of most interest is where the various case histories happen to plot in Figure 2.

Another method of comparing the various failures is in terms of brittleness index (I_B). Sladen et al. (1987) suggested that for slides that do not involve toe erosion, the brittleness index of the slope failure can be estimated by comparing initial and post-failure slope profiles using the following formula:

[1]
$$I_{\rm B} = \frac{\tan\beta_{\rm i} - \tan\beta_{\rm f}}{\tan\beta_{\rm i}}$$

where β_i and β_f are the initial and post-failure slope angles, respectively. This term is related to the relative slope ratio term discussed above. Note that the maximum possible value for I_B using Equation 1 is 1.0. Table 7 indicates that ten of the original Seed and Harder (1990) case histories have values of I_B greater than or equal to 0.64.

Sladen et al. (1985b) found that the brittleness index of a soil in undrained loading appears to be related to the state of a sandy soil, when measured in terms of the ratio of the initial mean normal effective stress of the soil to that at steady state at the same void ratio. Fear (1996) used the same measure of state for sandy soils and termed it reference state ratio (RSR). RSR is given by the following formula:

$$RSR = \frac{p'_i}{p'_{us}}$$

where p'_i is the initial mean normal effective stress and p'_{us} is the mean normal effective stress at ultimate (steady) state at the same void ratio. Note that p'_{us} is related to the deviator stress at ultimate state, q_{us} , by the following formula:

$$[3] M = \frac{q_{us}}{p'_{us}}$$

Estimating the average RSR for each case history is difficult. The best that can be done is to calculate an approximate single average value. The average value of p'_i was estimated based on the average value of σ'_{vo} given by Stark and Mesri (1992) for the middle of the liquefied layer and assuming a K_o of 0.5. The average value of p'_{us} was estimated by assuming an average M of 1.2 (which, for triaxial compression loading, corresponds to $\phi'_{us}=30^{\circ}$), assuming that $q_{us}=2S_u$, and using the mean value of Su in the Seed and Harder (1990) database. Clearly, the resulting average RSR is only an estimation and may be somewhat inaccurate. Nevertheless, it is interesting to compare the relationship between I_B and estimated RSR for the case histories in the original Seed and Harder (1990) database (with the exception of case history 2, for which the post-failure angle was not available, and case history 6, which was not a slope failure) with that suggested by Sladen et al. (1985b), as presented in Figure 3. Despite some scatter, there is definitely an observable increase in IB with increasing RSR, similar to that suggested by Sladen et al. (1985b). The only exceptions to this are the lateral spread case histories (8, 10, and 14), which have zero brittleness irrespective of the estimated RSR because no significant change in slope angle occurred as a result of each lateral spread.

Classification based on deformation characteristics

In general, as outlined in Table 2, all of the case histories in the database can be divided into three types of failures: flow failures, slump failures and lateral spreads. The category that a given case history falls into depends on its deformation characteristics as quantified by the various terms in Table 7. Case histories in the database classified as flow failures have large relative runouts (and large strains) and small slope angle ratios (and large values of I_B). As an

example, Figure 4(a) illustrates the flow failure at the Calaveras Dam (case history 1). Case histories in the database classified as lateral spreads have small relative runouts (and small strains), slope angle ratios of 1.0 (and I_B values of zero) and occur in gently sloping ground (i.e. initial slope angle $\leq 5^{\circ}$). As an example, Figure 4(b) illustrates the lateral spread at Whiskey Springs Fan (case history 14). Slump failures have deformation characteristics in between those of flow failures and those of lateral spreads. Case histories in the database classified as slump failures have smaller relative runouts (and smaller strains) and larger slope angle ratios (and smaller values of I_B) than the flow failures, but have large enough deformations in steeply sloping ground that they cannot be considered to be lateral spreads. As an example, Figure 4(c) illustrates the upstream and downstream slump failures at La Marquesa Dam (case records 15 and 16, respectively). The large deformations could have resulted from cyclic liquefaction combined with large earthquake motions.

This study has classified flow failures as those failures which had a relative runout of 2 or greater and a slope angle ratio of less than 0.4. Therefore, case histories 1, 3, 4, 7, 9, 13a & b, and 19 (Calaveras Dam, Fort Peck Dam, Solfatara Canal Dike, Uetsu Embankment, Mochi-Koshi Tailings, and Nerlerk Embankment, respectively) would be classified as flow failures (see data in Figure 2). Case histories 8, 10, and 14 (Snow River Bridge Fill, San Fernando Juvenile Hall, and Whiskey Springs Fan, respectively) would be classified as lateral spreads because they all had a relative runout less than 2, a slope angle ratio of 1 and occurred in gently sloping ground (initial slope angle $\leq 5^{\circ}$). Case histories 5, 12, 15, 16 and 17 (Lake Merced Bank, Upper San Fernando Dam, La Marquesa Dam - Upstream and Downstream, and La Palma Dam, respectively) would be classified as slump failures because they had relative runouts less than 2 and slope angle ratios greater than 0.4. Case histories 11 and 18 (Lower San Fernando Dam and Lake Ackerman, respectively) can be considered as borderline between the flow and slump categories.

The dividing line between a flow failure and a slump failure, as described above, is obviously somewhat subjective. It would be reasonable to expect some transition zone between flow and slump type failure deformation characteristics. Examining Figure 3, the dividing line between flow and slump failures in terms of brittleness index is an I_B of about 0.6. It is interesting to note that the classification of the individual case histories is similar to that by Baziar and Dobry (1995) who divided the database into flow slides, lateral spreads and major slides.

Flow Liquefaction versus Cyclic Softening

Robertson and Fear (1995), building on earlier work by Robertson (1994), proposed specific definitions of soil liquefaction, which distinguished between flow liquefaction (strain-softening response in undrained loading initiated by either a monotonic or cyclic trigger mechanism) from cyclic softening (progressive decrease in soil stiffness during cyclic loading). Cyclic softening was further divided into cyclic liquefaction (shear stress reversal occurs and zero effective stress can be reached) and cyclic mobility (no shear stress reversal occurs). A full description of these definitions is given by Robertson and Wride (1998) in a recent NCEER report on soil liquefaction (NCEER, 1998). It is often difficult, if not impossible, to distinguish between flow liquefaction (strain-softening response) and cyclic softening (liquefaction) phenomena in the field after a failure has occurred. Both types of liquefaction can result in large deformations. Ideally, instrumentation during and after a failure together with comprehensive site characterization would be required to correctly identify which phenomenon occurred. However, such information is not available for the case histories being discussed here. The best

that can be done is to make an estimate of which phenomenon controlled which case history, based on the terminology definitions described above and the observed deformation characteristics of each case history.

Statically triggered slope failures

Case histories 1 (Calaveras Dam), 3 (Fort Peck Dam), and 19 (Nerlerk Embankment) suffered failures as a result of static triggers. All three of these case histories have been classified as flow failures. Provided that failure truly occurred in the sand within each slope, these three case histories would have to be classified as cases of flow liquefaction, because the trigger was static. As indicated in Table 3, there is some ongoing debate over the influence of other factors such as weak clay shale or clay layers influencing the failure. However, it is possible that although strains may have first occurred in these weak layers, they may have been sufficiently large to trigger flow liquefaction in the strain-softening sand above, such that the overall failure was a result of the phenomenon of flow liquefaction.

Cyclically loaded case histories

Of the case histories in Table 2, one case history (21, Duncan Dam) did not fail, but consisted of field and laboratory studies investigating what conditions could lead to failure. Case history 6 (Kawagishi-Cho Building) differed from all of the other cyclically loaded case histories in that it consisted of the failure of a building foundation rather than deformations or failure of a slope. However, the remaining 16 case histories suffered some type of slope deformation as a result of cyclic loading. As discussed in the previous section, these case histories have been subdivided as to the nature of the deformation that occurred (see Table 2).

Lateral spreads

Four of the cyclically loaded case histories (8, 10, 14 and 20; Snow River Bridge Fill, San Fernando Juvenile Hall, Whiskey Springs Fan, and Heber Road, respectively) were lateral spreads, rather than severe slope failures. All four of these case histories had initial slope angles less than or equal to 5° and suffered no significant change in slope angle after failure. Each of these case histories suffered lateral deformations ("runouts") of less than or equal to 3 m. Youd (1993), based on earlier work by Bartlett and Youd (1992) included all four of these case histories within a database of lateral spread case histories. Since these lateral spreads occurred in level to gently sloping ground, it is reasonable to conclude that shear stress reversal did occur during the earthquake loading. Consequently, these lateral spreads are all likely deformations that are predominantly a result of cyclic softening (liquefaction).

Flow failures

Case histories 4, 7, 9, and 13a &b (Solfatara Canal Dike, Uetsu Embankment, Mochi-Koshi Tailings Dam 2 and Dam 1, respectively) were all cyclically loaded case histories that were classified as flow failures (see Figure 2). It is likely that these case histories suffered such large runout ratios and responded in such a brittle manner because they contained a sufficiently large mass of potentially strain-softening material that was triggered to strain-soften by the cyclic loading. Once triggered, the driving stresses were higher than the undrained shear strength and the material flowed significantly relative to the size of the slope or embankment. Thus, these case records are likely all cases of flow liquefaction. They can be grouped together with the statically triggered cases of flow liquefaction discussed earlier.

Slump failures

The slump failures are more difficult to classify as being controlled primarily by either flow liquefaction or cyclic softening (liquefaction). The observed slumping deformation pattern could be due to either type of liquefaction. If flow liquefaction occurred within the soil structure, there must have been an insufficient quantity of strain-softening material relative to strain-hardening material to result in a true flow failure. However, if shear stress reversal did occur within the soil structure, cyclic liquefaction with deformations accumulating during cyclic loading may have caused the observed deformations. In particular, if cyclic liquefaction occurred in the level ground at the toe of any of the slopes, the slumping deformation pattern may have been a result of the soil structure moving into the zone of softened soil. Further studies into all of the failures would be required to clearly identify what happened at each site. However, for interest, this study attempts to distinguish between possible flow liquefaction and possible cyclic softening.

Using results by Pando and Robertson (1995) as a guide, it is possible that shear stress reversal may have occurred within the slope of case histories 5, 15, 16 and 17 (Lake Merced Bank, La Marquesa Dam - Upstream and Downstream, and La Palma Dam, respectively) because they were all relatively short steep structures (see Table 2). In particular, shear stress reversal may have occurred in the level ground in the toe region of each slope, causing a loss in soil stiffness and resulting in the embankment slumping into the surrounding ground. Case history 6 (Kawagishi-Cho Building) may have been affected by a similar phenomenon.

Case history 12 (Upper San Fernando Dam) was a large enough structure that it is possible that

shear stress reversal may not have occurred throughout the structure. A more probable explanation is that the dam consisted of a small portion of strain-softening or limited strain-softening material such that it suffered damaging, but limited deformations, rather than a catastrophic flow failure. The presence of the downstream berm may have also contributed to limiting the deformations that occurred.

Case histories 11 and 18 (Lower San Fernando Dam and Lake Ackerman, respectively) which were considered as borderline between the flow and slump categories, may have contained more strain-softening material than case history 12, but still had an insufficient amount to result in relative runouts as high as most of the flow failure case histories. Also, the approximate RSR for the Lower San Fernando Dam was smaller than the approximate values of RSR calculated for the other case histories classified as flow failures (i.e. it appears to have had a denser initial state than the other flow failure case histories; see Table 7). Nevertheless, these two case histories will be included with the flow failure group because the deformations were fairly large and their slope angle ratios were low. The observation of a time delay between the end of the earthquake and the failure of the Lower San Fernando Dam supports the classification of the case history as flow liquefaction. However, the zone of material that suffered flow liquefaction was limited in size relative to the overall size of the dam, resulting in the borderline flow/slump deformations.

S_u versus $(N_I)_{60}$ for flow liquefaction case histories

Figure 5 presents a similar plot to that by Seed and Harder (1990) given in Figure 1, but includes only the case histories in the combined Seed and Harder (1990) and Stark and Mesri (1992) database which were classified as flow failures or borderline flow/slump failures (see Table 2).

These case histories are considered most likely to be cases of flow liquefaction, for which estimating an undrained strength is appropriate. Clearly, the data still falls within the Seed and Harder (1990) boundary lines because the values of S_u and $(N_1)_{60}$ -cs have not been changed. However, it is important to note that case histories 1, 2, 3, 4, and 7 had SPT values which were only estimated because little or no data were available (see Table 3 and Table 4). Therefore these data contain uncertainty; in particular, case histories 1 and 3, which have higher SPT values can be considered to have larger uncertainty associated with them than the lower blowcount case histories. Case history 19 had SPT values estimated from CPT measurements. Case history 11 consisted of highly interbedded silt and sand layers; hence, the average SPT blowcount can be misleading. If case histories 1, 3, 11 and 19 are removed from the plot because of the uncertainty associated with their SPT values, no case history data for flow failures are left with values of SPT (N_1)₆₀-cs > 6. Hence, the shape of the relationship for (N_1)₆₀-cs > 6 becomes uncertain.

Superimposed on Figure 5 is a theoretical ultimate state strength line (for triaxial compression direction of loading) for clean Ottawa sand (K_0 =0.5), based on the results of Fear and Robertson (1995). Also superimposed on Figure 5 are the results from the detailed site investigation and laboratory testing for case record 21 (Duncan Dam), as summarized in Table 6. The sand under investigation at Duncan Dam was essentially a clean sand, having a fines content of 5 to 8%. Consequently, essentially no blowcount correction is required for fines content and the measured (N_1)₆₀-in-situ values can be plotted directly on this figure. The data for Duncan Dam (which did not fail) certainly appear to follow the trend of the theoretical lines for Ottawa sand loaded in triaxial compression. For values of (N_1)₆₀-cs greater than about 10, both the Ottawa sand line and the Duncan Dam data certainly suggest a different trend to the relationship between S_u and (N_1)₆₀-cs than that suggested by the Seed and Harder (1990) boundary lines.

Representative Values of $(N_1)_{60}$ and S_u

Range of data reported in the literature

Table 1 summarized the values of $(N_1)_{60}$ (both in-situ and clean sand equivalent) and S_u used by Seed and Harder (1990). However, there is considerable uncertainty in the selected values and there appears to be a wide range of reported representative values of $(N_1)_{60}$ and S_u for each case history (as indicated in Table 4 and Table 5).

It is important to note, as outlined earlier (see Table 3), that several of the case histories in the Seed and Harder (1990) database had representative $(N_1)_{60}$ values selected based on no or little SPT data. In particular, case histories 1 and 3 (Calaveras Dam and Fort Peck Dam), which are two of the case histories with higher representative values of $(N_1)_{60}$ (see Figure 1), had $(N_1)_{60}$ values assigned based on relative density type estimates. Case history 16 (La Marquesa Dam, Downstream Slope), which was also one of the higher $(N_1)_{60}$ case histories (see Figure 1), appears to have a representative $(N_1)_{60}$ selected based on a single blowcount in the layer that appeared to have liquefied. Case history 14 (Whiskey Springs Fan had SPT values estimated from Becker penetration test (BPT) measurements. Case histories 11 and 12 (Lower and Upper San Fernando Dams, respectively) which had the highest representative $(N_1)_{60}$ values in the Seed and Harder (1990) database (see Figure 1). The selected values were extrapolated from post-earthquake conditions to pre-earthquake conditions and in the case of the Lower San Fernando Dam, from downstream conditions to upstream conditions. In addition, the

interbedded nature of the case history 11 and 12 deposits make the selection of an appropriate blowcount value difficult. Some of the uncertainties associated with the selection of representative values of S_u are discussed later in this paper.

Table 8 summarizes the range in values of $(N_1)_{60}$ -in-situ, S_u and estimated fines content, as reported by various authors and given in Table 4 and Table 5. Based on the estimated fines content, the values of $(N_1)_{60}$ -in-situ could be converted to equivalent clean sand values of $(N_1)_{60}$ -cs (after Seed, 1987). It is important to note that there is a considerable uncertainty with these fines content corrections. The data given for the case histories in Table 8 clearly cover a wider range than in Table 1, based on the Seed and Harder (1990) data alone.

A minimum $(N_1)_{60}$ approach

In general, the values of $(N_1)_{60}$ in the Seed and Harder (1990) chart appear to be average representative values for each case history. Experience has shown that the Seed and Harder (1990) chart often gives conservative estimates of S_u (e.g. Byrne et al., 1994), particularly when applied to all points in an SPT profile, including any low values. Based on the discussion in Fear and McRoberts (1995), it is likely the "weakest-link-in-the-chain", represented by the minimum $(N_1)_{60}$, that can result in either cyclic softening (liquefaction) or flow liquefaction being triggered at a particular site. Likewise, it could be argued that the resulting estimation of undrained shear strength for a liquefied soil deposit should be correlated with the minimum representative $(N_1)_{60}$, rather than the average value. Based on earlier work by Popescu (1997), Yoshimine et al. (1998) suggested that the 80-percentile value, or approximately the mean minus one standard deviation, of CPT data would be the appropriate value to link to undrained shear

strength. Since CPTs are continuous in nature and, particularly if several CPTs are conducted adjacent to one another, this calculation is fairly straightforward. However, when only limited SPT data are available, calculating a representative mean minus one standard deviation of $(N_1)_{60}$ is difficult. Therefore, selecting the minimum $(N_1)_{60}$ value may be a reasonable alternative.

Table 9 presents a summary of the revised values of S_u and $(N_1)_{60}$ chosen to represent each case history, based on the minimum $(N_1)_{60}$ viewpoint. A reasonable lower bound $(N_1)_{60}$ -in-situ was selected and the clean sand equivalent value was estimated based on the fines content and the SPT corrections proposed by Seed (1987). Table 9 provides comments regarding the selection of both S_u and $(N_1)_{60}$ for each case history. When possible, the value of S_u was selected as one which incorporated energy effects (Poulos, 1988; Davis et al., 1988), as this was felt to be closer to the "true" value of S_u . Conducting this exercise led to the conclusion that it is very difficult to represent a complex slope failure by a single S_u and a single $(N_1)_{60}$.

Although Table 9 presents the revised selections of S_u and $(N_1)_{60}$ for each of the case histories in the database, an undrained shear strength is really only appropriate for cases of flow liquefaction. While cases of cyclic softening (liquefaction) will likely experience deformations related to the minimum $(N_1)_{60}$, undrained shear strengths are not appropriate to the analysis of such a site. At best, they can represent equivalent values of S_u that would result in similar deformations as those caused by the progressive loss in soil stiffness. However, these values of S_u may not be appropriate for analyzing sites outside of the database.

Figure 6 presents the revised selection of S_u and $(N_1)_{60}$ -cs in Table 9 for the case histories in the combined Seed and Harder (1990) and Stark and Mesri (1992) database that were classified as

flow failures and borderline flow/slump failures. Superimposed on Figure 6 are the Seed and Harder (1990) boundary lines and the K_0 =0.5 theoretical line for clean Ottawa sand (Fear and Robertson, 1995). The general trend of the data appears to be more similar to the clean Ottawa sand line than the Seed and Harder (1990) boundary lines. However, the data are fairly limited and contain considerable scatter. If case histories 1, 3, 11 and 19 are removed due to the larger uncertainty in their SPT data, the shape of the relationship for $(N_1)_{60}$ -cs > 6 becomes uncertain.

The earlier discussion has suggested that undrained shear strengths only have real meaning for flow liquefaction case histories. Although an attempt has been made here to separate what appear to be true flow failures from other case histories in the database, some uncertainty remains as to which case histories should actually be included on a plot of S_u versus $(N_1)_{60}$ -cs. Therefore, Figure 7 presents the same plot as in Figure 6, but with all of the case histories shown, rather than just what are considered here to be true flow failures. Different symbols are used to distinguish each type of failure; i.e. flows and flow/slumps, slumps, lateral spreads, and the one building failure. Case history 5 (Lake Merced) is not shown in Figure 7 because an argument has been made in this study to remove it from the database (see Table 3 and Table 4). Similar conclusions can be drawn for Figure 7 as were drawn above for Figure 6.

Figure 8 presents the same data as in Figure 7, but in terms of undrained shear strength ratio. In order to normalize the values of undrained shear strength used in Figure 7, the values of σ'_{vi} selected by Stark and Mesri (1992) were used for each case history (see Table 7). However, for the Nerlerk Embankment case history (19), the value of S_u/σ'_{vi} of 0.148 selected by Stark and Mesri (1992) was used directly (see Table 5). Most of the flow failure case histories had values

of S_u/σ'_{vi} of less than 0.15. No data plot above an $(N_1)_{60}$ -cs of 10. However, in general, the data appear to suggest a different trend than that suggested by the Stark and Mesri (1992) boundary lines, which are shown in Figure 8 for comparison. Also shown for comparison $K_0=0.5$ theoretical line for clean Ottawa sand (Fear and Robertson, 1995).

Uncertainty with Su

In reviewing the case histories in the combined Seed and Harder (1990) and Stark and Mesri (1992) database, it soon becomes clear that there is considerable uncertainty in the selection of a representative value of S_u for an individual case history (see Table 4 and Table 5). As indicated in Table 3, many of the case histories involved "liquefaction" of a soil mass, while others (case histories 2, 10, 15, 16, 17, 18 and 20) involved "liquefaction" of a particular soil layer. For case histories involving failure of a soil mass, the zone occupied by the mass within the soil structure was sometimes limited in extent (e.g. case histories 11 and 12). Different assumptions were made by various authors as to the mechanics of failure in calculating a single representative S_u for each case history, resulting in the range of reported values presented in Table 8. For example, Lucia (1981) and Lucia et al. (1982) calculated S_u based on post-failure slope configurations, while Poulos (1988) and Davis et al. (1988) noted that the pre-failure and post-failure driving stresses would bracket the actual mobilized undrained shear strength and attempted to account for energy effects associated with the dynamics of failure when calculating the values of S_u .

In actual fact, a single value of S_u may reflect only the overall failure, but not apply everywhere within the failing soil mass or layer. Different directions of loading may occur at different points

within a soil structure such that various elements reach different values of S_u . However, many authors assume a single S_u along a failure surface. In addition, variability in soil state within the soil mass could result in different elements of soil having different values of S_u . Some failures (e.g. 19, Nerlerk embankment) were progressive in nature. If this is not accounted for, undrained strengths may not be properly estimated. Newmark type deformation analyses were often used to estimate the S_u that would result in the observed accumulated deformations during cyclic loading for the lateral spreading type case histories. However, the previous discussion has suggested that these deformations are generally due to a loss in soil stiffness during cyclic loading. While a value of S_u estimated using this method may match the observed deformations at a particular site, it is really only an equivalent S_u because the physics leading to failure did not necessarily involve a loss in strength. Extrapolating such results to other sites is not appropriate.

Deformations that result from the phenomenon of cyclic softening (liquefaction) should not be analyzed using an undrained shear strength in a stability analysis. Although the magnitude of the deformations that may occur will depend on the density of the soil (as indicated by $(N_1)_{60}$ values), they will also depend on the size and duration of cyclic loading. Other methods such as that developed by Youd (1993) should be used to estimate deformations associated with potential lateral spreads. Sloping ground that is not considered to be susceptible to flow liquefaction based on site specific testing should be carefully evaluated for the potential of cyclic softening (liquefaction) and resulting deformations. In such cases, it is important to carefully evaluate the level ground at the toe of a slope, in order to examine the effect that cyclic liquefaction and loss in stiffness within that zone may have on overall deformations of the slope. Similar investigations should be carried out for buildings located on level ground.

Conclusions

The empirical SPT-based chart by Seed and Harder (1990) is one of the most commonly used methods for estimating the undrained shear strength of sand for either statically or dynamically triggered flow liquefaction. This paper has illustrated the complexity and range of liquefaction failures contained within the combined Seed and Harder (1990) and Stark and Mesri (1992) database. It appears that the database contains a wide range of deformation characteristics and possibly a variety of flow liquefaction and cyclic softening case histories. However, after a failure has occurred, it is often very difficult to correctly identify which phenomenon controlled the observed deformations. In addition, the detailed summaries provided for each case history illustrate the difficulty in assigning a single S_u and a single $(N_1)_{60}$ to a complex slope failure.

Recent studies (e.g. Byrne et al., 1994; Fear and Robertson, 1995; Konrad and Watts, 1995; Yoshimine et al., 1998) have indicated that the undrained shear strength of sand is a flow liquefaction response parameter that is very sensitive to variability in a soil deposit as well as the direction of loading. These approaches often result in higher design strengths for denser soils than those predicted by the Seed and Harder (1990) chart. Nevertheless, the Seed and Harder (1990) chart continues to be considered by many workers and regulatory agencies as the most authoritative standard for assessing the undrained strength of liquefied soil.

However, the original relationships proposed by Seed and Harder (1990) appear to be conservative and based on average representative $(N_1)_{60}$ values for each case history. As a result, when applied in practice, they may be overly conservative for low points in any SPT $(N_1)_{60}$

profile in a soil deposit. In addition, the original database appears to contain limited reliable data for $(N_1)_{60}$ -cs > 6; thus, the shape of the relationship between S_u and $(N_1)_{60}$ -cs becomes uncertain. However, as suggested by other authors (e.g. Byrne et al., 1994; Konrad and Watts, 1995; Fear and Robertson, 1995; Yoshimine et al., 1998), the relationship may be extremely sensitive to small changes in density at values of $(N_1)_{60}$ -cs in the order of 10 to 15. When $(N_1)_{60}$ -cs falls above this threshold value, undrained strengths may be quite large. This is consistent with Fear and McRoberts' (1995) observation that a lower bound assessment of the Seed et al. (1984) seismic triggering database showed that seismic triggering was not observed above an $(N_1)_{60}$ of about 15.

Finally, when re-examined in view of some of the more recent concepts regarding soil liquefaction, it appears that the case histories in the original database are not inconsistent with alternative views and other recent developments in liquefaction. Thus, in practice, the revised database could be a useful tool which should be used in conjunction with other alternative approaches when assessing a particular site for instability due to flow liquefaction. The review of the database presented here assessed the case histories on a somewhat qualitative basis. Further studies into each of the individual case histories would be both interesting and useful in an attempt to answer some of the questions that are raised here and to assess the case histories in a more quantitative manner.

References

- Andrus, R.D. and Youd, T.L. 1987. Subsurface investigation of a liquefaction induced lateral spread - Thousand Springs Valley, Idaho. *Report prepared for the U.S. Army Corps of Engineers (miscellaneous paper GL-87-8)*, Department of Civil Engineering, Brigham Young University, Provo, Utah.
- Andrus, R.D., and Youd, T.L. 1989. Penetration tests in liquefiable gravels. *Proceedings of the* 12th International Conference on Soil Mechanics and Foundation Engineering, Rio de Janeiro, 1: 679-682.
- Andrus, R.D., Youd, T.L., and Carter, R.R. 1986. Geotechnical evaluation of a liquefaction induced lateral spread, Thousand Springs Valley Idaho. *Proceedings of the 22nd Annual Symposium on Engineering Geology and Soils Engineering*, Boise, ID, February 24-26, 1984.
- Bartlett, S.F., and Youd, T.L. 1992. Empirical analysis of horizontal ground displacement generated by liquefaction-induced lateral spread. *National Center for Earthquake Engineering Research, Technical Report NCEER-92-0021*.
- Baziar, M.H., and Dobry, R. 1995. Residual strength and large-deformation potential of loose silty sands. *Journal of Geotechnical Engineering*, ASCE 121(12): 896-907.
- Been, K., Crooks, J.H.A., Becker, D.E., and Jefferies, M.G. 1986. The cone penetration test in sands: part I, state parameter interpretation. *Géotechnique*, 36(2): 239-249.
- Been, K., Conlin, B.H., Crooks, J.H.A., Fitzpatrick, S.W., Jefferies, M.G., Rogers, B.T., and Shinde, S. 1987a. Back analysis of the Nerlerk berm liquefaction slides (Discussion). *Canadian Geotechnical Journal*, 24: 170-179.
- Been, K., Jefferies, M.G., Crooks J.H.A., and Rothenburg, L. 1987b. The cone penetration test in sands: part II, general inference of state. *Géotechnique*, 37(3): 285-299.

- Bennett, M.J. 1989. Liquefaction analysis of the 1971 ground failure at the San Fernando Valley
 Juvenile Hall, California. Bulletin of the Association of Engineering Geologists,
 26(2): 209-226.
- Byrne, P.M., Imrie, A.L., and Morgenstern, N.R. 1994. Results and implications of seismic performance studies for Duncan Dam. *Canadian Geotechnical Journal*, 31:-979-988.
- Casagrande, A. 1965. Role of the 'calculated risk' in earthwork and foundation engineering. The Terzaghi Lecture, *Journal of the Soil Mechanics and Foundations Division*, Proceedings of the ASCE, 91(SM4): 1-40.
- Davis, Jr., A.P., Castro, G. and Poulos, S.J. 1988. Strengths backfigured from liquefaction case histories. Proceedings of the Second International Conference on Case Histories in Geotechnical Engineering, St. Louis, Mo., Paper No. 4.35, 1693-1701.
- De Alba, P.A., Seed, H.B., Retamal, E., and Seed, R.B. 1988. Analysis of dam failures in 1985 Chilean earthquake. *Journal of Geotechnical Engineering*, ASCE, 114(12): 1414-1434.
- Department of Water Resources 1989. Examination of the performance of Upper San Fernando
 Dam during the earthquake of February 9, 1971. Addendum F of Bulletin 203-88
 (The August 1, 1975, Oroville Earthquake Investigation, Supplement to Bulletin 203-78),
 The Resources Agency, State of California.
- Fear, C.E. 1996. In-situ testing for liquefaction evaluation of sandy soils, *Ph.D. Thesis*, University of Alberta, Edmonton, Alberta, Canada.
- Fear, C.E., and McRoberts, E.C. 1995. Reconsideration of initiation of liquefaction in sandy soils, Journal of Geotechnical Engineering, ASCE 121(3): 249-261.
- Fear, C.E., and Robertson, P.K. 1995. Estimating the undrained shear strength of sand: a theoretical framework, Canadian Geotechnical Journal, 32(5): 859-870.

- GEI Consultants 1988. Re-evaluation of the Lower San Fernando Dam, an investigation of the February 9, 1971 slide. *Submitted to U.S. Army Corps of Engineers, Waterways Experiment Station*, 2 Volumes.
- Gu, W.H. 1992. Liquefaction and post-earthquake deformation analysis. *Ph.D. Thesis*, University of Alberta, Edmonton, Alberta, Canada.
- Harder, L.F. 1988. Use of penetration tests to determine the cyclic loading resistance of gravelly soils during earthquake shaking. *Ph.D. Thesis*, Department of Civil Engineering, University of California, Berkeley.
- Hazen, A. 1918. A study of the slip in the Calaveras Dam. *Engineering News-Record*, 81(26): 1158-1164.
- Hazen, A. and Metcalf, L. 1918. Middle section of upstream side of Calaveras Dam slips into reservoir. *Engineering News-Record*, 80(14): 679-681.
- Hryciw, R.D., Vitton, S., and Thomann, T.G. 1990. Liquefaction and flow failure during seismic exploration. *Journal of Geotechnical Engineering*, 116 (12): 1881-1899.
- Ishihara, K. 1984. Post-earthquake failure of a tailings dam due to liquefaction of the pond deposit. Proceedings of the International Conference on Case Histories in Geotechnical Engineering, St. Louis, Mo, May 6-11, 3: 1129-1146.
- Ishihara, K., and Koga, Y. 1981. Case studies of liquefaction in the 1964 Niigata earthquake, Soils and Foundations, 21(3): 35-52.
- Jefferies, M.G., Been, K., and Hachey, J.E. 1990. Influence of scale on the constitutive behaviour of sand. *Proceedings of the 43rd Canadian Geotechnical Conference, Laval University*, 1: 263-273.
- Konrad, J.-M., and Watts, B.D. 1995. Undrained shear strength for liquefaction flow failure analysis, Canadian Geotechnical Journal, 32(5): 783-794.

- Lee, K.L., Seed, H.B., Idriss, I.M., and Makdisi, F.I. 1975. Properties of soil in the San Fernando hydraulic fill dams. *Journal of Geotechnical Engineering*, ASCE, 101(GT8): 801-821.
- Little, T.E., Imrie, A.S., Psutka, J.F. 1994. Geologic and seismic setting pertinent to dam safety review of Duncan Dam. *Canadian Geotechnical Journal*, 31: 919-926.
- Lucia, P.C. 1981. Review of experiences with flow failures of tailings dams and waste impoundments. *Ph.D. Thesis*, University of California, Berkeley.
- Lucia, P.C., Duncan, J.M. and Seed, H.B. 1982. Summary of research on case histories of flow failures of mine tailings impoundments. *Proceedings of the Workshop on Mine Waste Disposal Technology*, Denver, Colorado, Bureau of Mines Information Circular 8857.
- Marcusen, W.F. III, and Krinitzsky, E.L. 1976. Dynamic analysis of Fort Peck Dam. *Technical Report S-76-1*, U.S. Army Engineer Waterways Experiment Station, Vicksburg, Miss.
- Marcusen, W.F. III, Ballard, R.F., Jr., and Ledbetter, R.H. 1979. Liquefaction failure of tailings dams resulting from the near Izu Oshima earthquake, 14 and 15 January, 1978. *Proceedings, 6th Pan-American Conference on Soil Mechanics and Foundations Engineering*, Lima, Peru.
- McRoberts, E.C., and Sladen, J.A. 1992. Observations on static and cyclic sand liquefaction methodologies. *Canadian Geotechnical Journal*, 29, 4.
- Middlebrooks, T.A. 1940. Fort Peck slide (with discussions by Messrs. J. Field, J.D. Justin, W. Gerig, A.J. Ryan, G. Gilboy, F.E. Fahlquist, I.B. Crosby and T.A. Middlebrooks). ASCE Transactions, Paper No. 2144, 723-764.
- Mishima, S., and Kimura, H. 1970. Characteristics of landslides and embankment failures during the Tokachioki earthquake. *Soils and Foundations*, 10(2): 39-51.
- NCEER 1998. Proceedings of the NCEER workshop on evaluation of liquefaction resistance of soils, Salt Lake City, Utah, January 1996, Edited by T.L. Youd and I.M. Idriss.

- Pando, M., and Robertson, P.K. 1995. Evaluation of shear stress reversal due to earthquake loading for sloping ground, *Proceedings of the 48th Canadian Geotechnical Conference*, Vancouver, B.C., 2: 955-962.
- Pillai, V.S., and Salgado, F.M. 1994. Post-liquefaction stability and deformation analysis of Duncan Dam. *Canadian Geotechnical Journal*, 31: 967-978.
- Pillai, V.S., and Stewart, R.A. 1994. Evaluation of liquefaction potential of foundation soils at Duncan Dam. *Canadian Geotechnical Journal*, 31: 951-966.
- Plewes, H.D., Pillai, V.S., Morgan, M.R., and Kilpatrick, B.L. 1994. In situ sampling, density measurements, and testing of foundation soils at Duncan Dam. *Canadian Geotechnical Journal*, 31: 927-938.
- Popescu, R., Prevost, J.H., and Deodatis, G. 1997. Effects of spatial variability on soil liquefaction: some design recommendations, Geotechnique, 47(5): 1019-1036.
- Poulos, S.J. 1988. Liquefaction and related phenomena. Advanced Dam Engineering for Design, Construction, and Rehabilitation, R.B. Jansen (ed.), Van Nostrand Reinhold, New York, 292-320.
- Robertson, P.K. 1994. Suggested terminology for liquefaction. Proceedings of the 47th Canadian Geotechnical Conference, Halifax, Nova Scotia, 277-286.
- Robertson, P.K., and Fear, C.E. 1995. Liquefaction of sands and its evaluation. Keynote Lecture,
 Proceedings, IS Tokyo '95, 1st International Conference on Earthquake Geotechnical Eng.,
 Edited by K. Ishihara, Balkema, Rotterdam, 3: 1253-1289.
- Robertson, P.K., and Wride (née Fear), C.E. 1998. Cyclic liquefaction and its evaluation based on the SPT and CPT, Final submission to the 1996 NCEER Workshop on Evaluation of Liquefaction Resistance (T.L. Youd, Chair).

- Rogers, B.T., Been, K., Hardy, M.D., Johnson, G.J., and Hachey, J. 1990. Re-analysis of Nerlerk B-67 berm failures. *Proceedings of the Canadian Geotechnical Engineering Conference*, Laval University, 1, 227-237.
- Ross, G.A. 1968. Case studies of soil stability problems resulting from earthquakes. *Ph.D. Thesis*, University of California at Berkeley.
- Ross, G.A., Seed, H.B., and Migliaccio, R.R. 1969. Bridge foundations in Alaska earthquake. Journal of Soil Mechanics and Foundations Division, ASCE, 95(4): 1007-1036.
- Seed, H.B. 1969. Analysis of Sheffield Dam failure. *Journal of the Soil Mechanics and Foundations Division*, Proceedings of the ASCE, 95(SM 6): 1453-1490.
- Seed, H.B. 1979. Considerations in the earthquake-resistant design of earth and rockfill dams. The Rankine Lecture, *Géotechnique*, 29(3): 215-263.
- Seed, H.B. 1987. Design problems in soil liquefaction. *Journal of Geotechnical Engineering*, ASCE 113(8): 827-845.
- Seed, R.B., and Harder, L.F. 1990. SPT-based analysis of cyclic pore pressure generation and undrained residual strength. *Proceedings of the H. Bolton Seed Memorial Symposium*, 2, 351-376.
- Seed, H.B., Idriss, I.M., Lee, K.L., and Makdisi, F.I. 1975. Dynamic analysis of the slide in the lower San Fernando Dam during the earthquake of February 9, 1971. *Journal of the Geotechnical Engineering Division*, ASCE, 101(GT9): 889-912.
- Seed, H.B, Tokimatsu, K., Harder, L.F., and Chung, R.M. 1984. The influence of SPT procedures in soil liquefaction resistance evaluations. *Earthquake Engineering Research Center Report No. UCB/EERC-84/15*, College of Engineering, University of California, Berkeley, California.

- Seed, H.B., Seed, R.B., Harder, L.F., and Jong, H-L. 1988. Re-evaluation of the slide in the Lower San Fernando dam in the earthquake of Feb. 9, 1971. *Report No. UCB/EERC-88/04, Earthquake Engineering Research Center*, University of California, Berkeley.
- Sego, D.C., Robertson, P.K., Sasitharan, S., Kilpatrick, B.L., and Pillai, V.S. 1994. Ground freezing and sampling of foundation soils at Duncan Dam. *Canadian Geotechnical Journal*, 31: 939-950.
- Skempton, A. W. 1986. Standard penetration test procedures and the effects in sands of overburden pressure, relative density, particle size, ageing and overconsolidation. *Geotechnique*, 36(3): 425-447.
- Sladen, J.A. 1989a. Cone penetration test calibration for Erksak (Beaufort Sea) sand: Discussion. *Canadian Geotechnical Journal*, 26: 173-177.
- Sladen, J.A. 1989b. Problems with interpretation of sand state from cone penetration test. *Géotechnique*, 39(2): 323-332.
- Sladen, J.A., and Hewitt, K.J. 1989. Influence of placement method on the in situ density of hydraulic sand fills. *Canadian Geotechnical Journal*, 26: 453-466.
- Sladen, J.A., D'Hollander, R.D., Krahn, J. and Mitchell, D.E. 1985a. Back analysis of the Nerlerk berm liquefaction slides. *Canadian Geotechnical Journal*, 22: 579-588.
- Sladen, J.A., D'Hollander, R.D., and Krahn, J. 1985b. The liquefaction of sands, a collapse surface approach. *Can. Geotech. J.*, 22: 564-578.
- Sladen, J.A., D'Hollander, R.D., Krahn, J. and Mitchell, D.E. 1987. Back analysis of the Nerlerk berm liquefaction slides: Reply. *Canadian Geotechnical Journal*, 24: 179-185.
- Stark, T.D., and Mesri, G.M. 1992. Undrained shear strength of liquefied sands for stability analysis. *Journal of Geotechnical Engineering*, ASCE, 118 (11): 1727-1747.

- U.S. Army Corps of Engineers 1939. Report on the slide of a portion of the upstream face of the Fort Peck Dam, Fort Peck, Montana. U.S. Government Printing Office, Washington.
- Yamada, G. 1966. Damage to earth structure and foundations by the Niigata earthquake June 16, 1964, in JNR. *Soils and Foundations*, 6(1): 1-13.
- Yoshimine, M., Robertson, P.K., and Wride, C.E. Undrained shear strength of clean sands. Submitted to the Canadian Geotechnical Journal.
- Youd, T. L. 1993. Liquefaction-induced lateral spread displacement. *Technical Note N-1862*, Naval Civil Engineering Laboratory, Port Hueneme, California.
- Youd, T.L. and Bennett, M.J. 1983. Liquefaction sites, Imperial Valley, California. Journal of Geotechnical Engineering, ASCE, 109(3): 440-457.
- Youd, T.L., Harp, E.L., Keefer, D.K., and Wilson, R.C. 1985. The Borah Peak, Idaho
 Earthquake of Oct. 28, 1983 -- liquefaction. *Earthquake Spectra*, Earthquake Engineering
 Research Institute, 2(1).

Table 1. Summary of the data by Seed and Harder (1990)

	Case History		Su	n		e	$(N_1)_{60}$	FC
No.	. Name	u	mean		+/-	in-situ	clean sand	(%)
		(psf)	(kPa)	(Jsd)	(kPa)		equivalent	
******	Calaveras Dam	650	31.1	50	2.4	٢	1	>60*
0	Sheffield Dam	75	3.6	25	01	. ₽		ος 15‡
ŝ	Fort Peck Dam	350	16.8	100	- -	- ~	01	04 *04
4	Solfatara Canal Dike	50	2.4	25	1.2) 4	4	• • • • •
S	Lake Merced Bank	100	4.8	0	0.0	. 9	9) (r
9	Kawagishi-Cho Building	120	5.7	0	0.0	4	4	CS^{*}
7	Uetsu Railway Embankment	40	1.9	0	0.0	m	ŝ	CS^{\dagger}
∞	Snow River Bridge Fill	50	2.4	0	0.0	5.5	- L	15+
6	Koda Numa Embankment	50	2.4	0	0.0	"	. (1	
10	San Fernando Juvenile Hall	130	6.2	70	3.4	9	10.5	27 65
11	Lower San Fernando Dam	400	19.2	100	4.8	11.5	13.5	20 20
12	Upper San Fernando Dam	600	28.7	100	4.8	13	15	04 V
13a	Mochi-Koshi Tailings -Dam 2	250	12.0	150	7.2) C) v	07 80
13b	-Dam 1	1	1	1		>)	00
14	Whiskey Springs Fan	150	7.2	10	0.5	×	1 1	
15	La Marquesa Dam - U/S Slope	200	9.6	120	5.7	9 4	y Y	04
16	La Marquesa Dam - D/S Slope	400	19.2	150	2 L	- 0	o 1	
17	La Palma Dam	200	9.6	100	4.8	Ś	T 7	15
appr	* approximate values based on data from Poulos (1988);		estimated for this study; [‡] assumed to be clean sand (CS)	study; [‡] assur	ned to be clear	ו sand (CS)		

34

by Seed (1987): $\Delta(N_1)_{60} = 1, 2, 4$ and 5 for FC = 10%, 25%, 50% and 75%, respectively

history statistics
of case
Summary of case
Table 2.

	Case History	Initial Slop	Initial Slope Geometry	Type of	ЕQ	amar	Type of	Post-failure Geometry	Geometry
No.	Name	Height*	Angle [†]	Trigger	Magnitude		Failure	Runout [‡]	Angle
		(m)	(_)					(m)	e ()
	Calaveras Dam	61	18.4	construction	N/A	N/A	flow	183	5 71
~	Sheffield Dam	7.6	21.8	EO		015	flow	30	11.0
~	Fort Peck Dam	61	14	construction		N/A	flow	751	
	Solfatara Canal Dike	2.1	27	EO	7.1	0.1 - 0.33	flow	407 22	2.60 3.6
	Lake Merced Bank	9.8	34	ĒQ		0.12	slump	18	0.0 24
9	Kawagishi-Cho Building	0	0	EQ	7.5	1	building foundation	2 0	 N/A
~	Uetsu Railway Embankment	10	29	ЕQ	7.5	I	flow	115	4
~	Snow River Bridge Fill	ŝ	1.25	EQ	9.2	I	lateral spread	6	. 1
~	Koda Numa Embankment	ę	30	EQ	8.1	1	flow	18	Ì
0	San Fernando Juvenile Hall	30	1.5	ÉO	6.5	0.5	lateral enread	0.75	+ <u>'</u>
	Lower San Fernando Dam	43	21.8	ĔQ	6.5	0.5 - 0.55	flow/shimn	61.0	0.13 8 13
	Upper San Fernando Dam	17.6	21.8	ĒQ	6.5	0.5 - 0.6	shimn	15	01.0 8 1 C
	Mochi-Koshi Tailings -Dam 2	20	20.1	ĒQ	7	0.1 - 0.25	flow	240	0.12 A S
13b	-Dam 1	30	20.1	EO	٢	01-025	flow	2002	
4	Whiskey Springs Fan	9.1	5	EO	.9	0.4	lateral snread		4.U A
[5]	La Marquesa Dam - U/S Slope	7.9	27	ΕÓ	~	0.6	shimm	11	ں د م
16	La Marquesa Dam - D/S Slope	7	34	ΕÓ	8	0.6	dumic	7 Y Y	U.21
~	La Palma Dam	11	34	ΕÓ	8	0.46	dumic		0 [
~	Lake Ackerman	6.4	26.6	seismic explor.	N/A	CSR = 0.12	flour/ehimn) [- u - t
19	Nerlerk Embankment	24	12.65	construction	N/A	N/A	dirimte wort	71	C./
20 I	Heber Road	0	0	EQ	6.55	>0.8	lateral spread	1.65	0.1
21 I	Duncan Dam	39	11.3	N/A	6.5	0.12	N/A	N/A	N/A

 $^{+}$ If a slope was stepped, the initial slope angle represents most of the slope.

[‡] Runout was defined as the horizontal distance from the toe of the original slope to the toe of the post-failure slope.

by Ross (1968). 3. At San Fernando Juvenile Hall, there was a 30 m height difference between the toe and head of the slide since the lateral spread was 1.2 km long. 4. At Whiskey Springs Fan, there was a 9.1 m height difference between the toe and head of the slide since the lateral spread was 60 m long. 5. Details given for Nerlerk Embankment Notes: 1. Not enough information was given by Seed (1969) to estimate the post-failure slope angle for Sheffield Dam. 2. Details for Lake Merced Bank refer to Slide 1 reported refer to the largest slide in 1983 (Slide 3). 6. At Heber Road, the ground was essentially level ground (i.e. slope angle $\approx 0^{\circ}$); thus there was essentially no height difference between the toe and head of the spread area; horizontal displacements at Heber Road ranged from 4 ft to 7 ft at the road and canal, respectively; the average horizontal displacement was 5.5 ft (1.65 m). 7. The EQ data given for Duncan Dam are the design values.
Funct Failure Failure Failure Frage mass Indica on capacity Stillery a taging straight Structure Failure Pregrassion andion capacity stillery a taging 193 X hydraulic fill dam upstream Inscription at light spression 1925 X hydraulic fill dam upstream Inscription at light spression 1925 X hill road embankment along lake upstream Inscription x X at 1925 X hill road embankment along lake into lake mass X X X att 1964 X hill road embankment along lake into hild threetons mass X X X att 1964 X hill road embankment along lake into hild threetons mass X X att 1964 X hill road embankment along lake into hild threetons mass X X att 1964 X hill road embankment along lake downstream <t< th=""><th></th><th>Case History</th><th>Year of</th><th>No SPT Data</th><th>Reported</th><th></th><th>Direction of</th><th></th><th></th><th>Nature</th><th>Nature of failure</th><th></th></t<>		Case History	Year of	No SPT Data	Reported		Direction of			Nature	Nature of failure	
Sheffield Dam 1918 X hydraulic fill dam upstream mass X Fert Fect Dam 1923 X downstream layer mass X X Fert Fect Dam 1933 X downstream layer mass X X Fert Fect Dam 1937 X* fill road enbankment into wy from canal mass X X Lake Mercel Bank 1940 X* fill road enbankment into wy from canal mass X X Store River Dam 1964 X railway enbankment into with direction only mass X Store River Dam 1971 post-EQ DS only X highway enbankment into direction only mass X Kawagishi-Cho Building 1971 post-EQ DS only X highway enbankment into direction only mass X Koda Numa Embankment 1971 post-EQ DS only X highway enbankment into direction only mass X Koda Numa Embankment		Natio	Fauure		as highly stratified deposit	Structure	Failure	Failed soil: large mass or distinct	Hinge-type motion observed	1	Reported as likely rogressive	Possibly associated with some weak shale
British Dam 1925 X dam dowstream layer beneath dam X X For Peck Dam 1938 limited hydraulic fill dam way from canal mass X X Soffarar Canal Dike 1940 X into alke into alke mass X X Kanagishi-Cho Building 1940 X into alke into alke mass X X Kanagishi-Cho Building 1964 X into alke into alke mass X X Kanagishi-Cho Building 1964 X into alke into alke mass X Kanagishi-Cho Building 1964 X intolwatterent into alke mass X Kanagishi-Cho Building 1971 1071 mass X mass X Koda Num Frando Juwelle Hall 1071 serf V potentile fill dam downstream mass X Kola Num Frando Juwelle 1071 serf V potentile fill dam downstream mass X <td>-</td> <td>Calaveras Dam</td> <td>1918</td> <td>X</td> <td></td> <td>hydraulic fill dam</td> <td>unstream</td> <td>mass</td> <td>*</td> <td></td> <td></td> <td>or clay base layer</td>	-	Calaveras Dam	1918	X		hydraulic fill dam	unstream	mass	*			or clay base layer
Fort Peck Dam 133 Initial hydratic fill dam wystream mass X Lek Mered Bank 1937 X Ill rod erendia long lok N/A mass X Lake Mered Bank 1937 X Ill rod erendia long lok N/A mass X Kawagishry Erhankment 1964 X building on level ground wwsishe mass X Kawagishry Erhankment 1964 X building on level ground wwsishe X Sow Ner Bridge Fill 1971 post<-EQ DS only	3	Sheffield Dam	1925	×		dam	downstream	laver henesth dam	< >		>	
Solifarta Caral Dike 1940 X i live e of a canal avay fram canal mass into lake more shown in the lake more and the more of a canal verse for a canal for a constone mass verse for a canal verse for a canal verse for a canal verse for a canal verse for a constone mass verse for a verse for a verse for a construct mass verse for a verse for a construct mass verse for a verse verse for a verse v	ŝ	Fort Peck Dam	1938	limited		hvdraulic fill dam	IInstream	iaju ouicaui uaili maee	< >		×	\$
Lake Merced Bank 1957 X+ fill road embankment along lake mino lake <thmino lake<="" th=""> mino lake mino lake</thmino>	4	Solfatara Canal Dike	1940	×		levee of a canal	awav from canal	20011	<			×
Kawagesh-Cho Building 1954 X ¹ building on level ground N/A mass X Ueswagesh-Cho Building 1964 X railway embankment io on an enderiction only mass X User Railway Embankment 1968 X inighay embankment io on an enderiction only mass X Sow River Bild 1971 1964 X highay embankment in on directions mass X Sow River Bild 1971 post-EQ DS only X hydraulic fill dam uownstream mass X Sow River Bild 1971 post-EQ DS only X hydraulic fill dam uownstream mass X Upper San Fernando Jam 1971 post-EQ DS only X hydraulic fill dam uownstream mass X Upper San Fernando Jam 1973 Waraues X talings dam downstream mass X Upper San Fernando Jam 1973 Marques Jore downstream mass X Marques 1983	ŝ	Lake Merced Bank	1957	*X		fill road embankment along lake	into lake	mass				
Uesta Ralway Embanikent 1964 X trailway embanikent in one direction only mass Sonow Kiver Bridge Fill 1971 1964 X trailway embanikent 1964 trailway file Sonow Kiver Bridge Fill 1971 1971 1971 1971 trailway file trailway file San Fernando Juvenile Hall 1971 1971 post-EQ D/S only X hydraulic fill dam upsettram mass Lower San Fernando Juvenile Hall 1971 post-EQ D/S only X hydraulic fill dam upsettram mass X Monti-Koshi Tings - Dam 1 1973 post-EQ D/S only X hydraulic fill dam upsettram mass X Molick Spring Fan 1973 post-EQ D/S only X hydraulic fill dam downstream mass X Molick Spring Fan 1973 post-EQ D/S only X talings dam downstream mass X Molick Spring Fan 1973 post-EQ D/S only X talings dam downstream mass Monti-Koshi Tings - Dam 1/U Spring Fan 1973 post-EQ D/S only X talings dam downstream mass I a Marquess Dam - U/S Stope 1985 post-EQ D/S only post-Eq P/Stope	9	Kawagishi-Cho Building	1964	*‡		building on level ground	N/A	336 (LI		>		
Snow Kiver Bridge Fill 1964 bridges crossing river bed downslope mass Koda Numa Embankment 1971 1971 1971 1971 1971 aver highway embankment in boh directions mass San Fernando Dam 1971 1971 1971 post-EQ D/S only X hydraulic fill dam downstream mass X Mochris/Koshi Talings Dam1 1978 X hydraulic fill dam downstream mass X Mochris/Koshi Talings Dam1 1978 X hydraulic fill dam downstream mass X Mochris/Koshi Talings Dam1 1978 Error Value downstream mass X Wiskey Springs Fan 1978 BPT data only genty sloping ground downstream mass X La Marquesa Dam - U/S Slope 1983 BPT data only genty sloping ground upstream layer beneath dam La Marquesa Dam - U/S Slope 1983 CPT data only genty sloping ground upstream layer beneath dam	7	Uetsu Railway Embankment	1964	×		railwav embankment	in one direction only	550111		<		
Koda Numa Embankment 1968 X highway embankment in boundarops mass mass x Sar Ferrando Dam 1971 post-EQ DS only X hydraulic fill dam downslope layer Lower San Fernando Dam 1971 post-EQ DS only X hydraulic fill dam downslope layer Lower San Fernando Dam 1971 post-EQ DS only X hydraulic fill dam downslope layer Upper San Fernando Dam 1971 post-EQ DS only X hydraulic fill dam downslope layer Mochi-Koshi Talings Jam 1973 BPT data only talings dam downstream mass X Winkey Springs Fam nass talings dam downstream mass X Winkey Springs Fam 1973 genty sloping ground downstream layer beneath dam La Marquesa Dam - U/S Slope 1985 genty sloping ground downstream layer beneath dam La Marquesa Dam - U/S Slope 1987 torage reservoir dam upstream layer beneath dam	00	Snow River Bridge Fill	1964			bridges crossing river hed	downslone	220111				
San Fernando Juvenile Hall 1971 1971 post-EQ D/S only X bydraulic fill dam downstream mass X Lower San Fernando Dam 1971 post-EQ D/S only X bydraulic fill dam downstream mass X Mochi-Koshi Tailings Dam 1 1973 post-EQ D/S only X bydraulic fill dam downstream mass X Mochi-Koshi Tailings Dam 1 1978 tata only gently sloping ground downstream mass X Mixetv Springs Fan 1983 BPT data only gently sloping ground downstream mass X Marquesa Dam -U/S Slope 1983 BPT data only gently sloping ground downstream layer X La Marquesa Dam -U/S Slope 1983 RPT data only gently sloping ground downstream layer X La Palma Dam 1983 CPT data only storage reservoir dam upstream layer layer X La Marquesa Dam 1979 gently sloping ground downstream layer layer layer Iayer La Palma Dam<	6	Koda Numa Embankment	1968	×		highway embankment	in hoth directions	CCDIII				
Lower San Fernando Dam 1971 post-EQ DS only X Indraulic fill dam uownstope layer Upper San Fernando Dam 1971 post-EQ DS only X hydraulic fill dam uownstream lass X Upper San Fernando Dam 1971 1978 X hydraulic fill dam downstream lass X Nochi-Koshi Talings -Dam 1978 etalings dam downstream mass X Morti-Koshi Talings -Dam 1978 key trainings dam downstream mass X Morti-Koshi Talings -Dam 1978 key trainings dam downstream mass X Morti-Koshi Talings -Dam 1978 key trainings dam downstream mass X Miskey Springs Fan 1983 BPT data only genty sloping ground downstream layer beneath dam K La Marquess Dam 1987 storage reservoir dam upstream layer beneath dam layer beneath dam La Marquess Dam 1987 CPT data only storage reservoir dam upstream layer beneath dam layer beneath dam	10	San Fernando Juvenile Hall	1971			dently cloning around		IIIdSS				
Upper San Fernando Dam 1971 X hydrautic fil dam upper can fumited) mass X Mochi-Koshi Tailings Dam 1 1978 Y tailings dam downstream mass X Mochi-Koshi Tailings Dam 1 1978 Total 1978 tailings dam downstream mass X Dam 1 1978 Total tailings dam downstream mass X Marquesa Dam - U/S Slope 1983 BPT data only gently sloping ground downstream mass X La Marquesa Dam - U/S Slope 1983 CPT data only gently sloping ground downstream layer beneath dam La Palma Dam 1983 CPT data only storage reservoir dam upstream layer beneath dam La Palma Dam 1983 CPT data only storage reservoir dam upstream layer beneath dam La Palma Dam 1983 CPT data only storage reservoir dam upstream layer beneath dam La Palma Dam 1983 CPT data only storage reservoir dam upstream layer beneath dam La Palma Dam N/A	11	Lower San Fernando Dam		tost-EO D/S only	×	budraulio fill dam	nowiisiope	layer			1	
Mochi-Koshi Tailings -Dan 21978nutature un damdownstream (minted)mass-Dan 11978-Dan 11978nutative units damdownstream (minted)mass-Dan 11978-Dan 11978tailings damdownstream (massx-Dan 11978-Dan 11978tailings damdownstream (massx-Dan 11973BPT data onlygently sloping grounddownstream (massx-Dan 20/S Slope1985storage reservoir damupstream (averse) and and storage reservoir damupstream (averse) and aver beneath damLa Marquesa Dam - D/S Slope1985storage reservoir damupstream (averse) and aver beneath dam10851979gently sloping grounddownstream (averse) and averlayer beneath damLake Ackerman1973CPT data onlystorage reservoir damupstream (averse) and averLake Ackerman1983CPT data onlystorage reservoir damupstream (averse) and averLake Ackerman1983CPT data onlystorage reservoir damupstream (averse) and averLake Ackerman1983CPT data onlystorage reservoir damupstreamLake Ackerman1983CPT data onlystorage reservoir damupstreamLake Ackerman1983cPT data onlysubset hydraulic fill road embankmentinto lakeLake Ackerman1983cPT data onlysubset hydraulic fill road embankmentinto lakeNicher Road1979cPT data onlysubset hydraulic fill road emban	12	Upper San Fernando Dam			< >		upstream	mass			×	
Dam 1 1978 uniting dam downstream mass x Uhiskey Springs Fan 1983 BPT data only tailings dam downstream mass x La Marquesa Dam - U/S Slope 1985 BPT data only gently sloping ground downstream mass x La Marquesa Dam - U/S Slope 1985 storage reservoir dam upstream layer beneath dam x La Marquesa Dam - D/S Slope 1985 storage reservoir dam upstream layer beneath dam La Marquesa Dam - D/S Slope 1985 storage reservoir dam upstream layer beneath dam La Marquesa Dam - D/S Slope 1985 storage reservoir dam upstream layer beneath dam La Rekerman 1983 CPT data only storage reservoir dam upstream layer beneath dam La Rekerman 1983 CPT data only storage reservoir dam upstream layer beneath dam La Rekerman 1983 CPT data only subractions greet dam into lake layer Name 1983 CPT data only subraction ground downstream layer Netlerk Embankment 1983 CPT data only subraction ground various directions layer Heber Road 1970<	13a		1978		<		downstream (limited)	mass				
Whiskey Springs Fan1983BPT data onlytautugs damdownstreammassLa Marquesa Dam - U/S Slope1983BPT data onlygently sloping grounddownslopemassLa Marquesa Dam - U/S Slope1983BPT data onlygently sloping grounddownslopemassLa Marquesa Dam - D/S Slope1985storage reservoir damupstreamlayer beneath damLa Marquesa Dam - D/S Slope1985storage reservoir damupstreamlayer beneath damLake Ackerman1987storage reservoir damupstreamlayer beneath damLake Ackerman1983CPT data onlystorage reservoir damupstreamlayer beneath damLake Ackerman1983CPT data onlystorage reservoir damupstreamlayer beneath damLake Ackerman1979gently sloping grounddownslopelayerlayerLake Ackerman1979storage reservoir damupstreamlayer beneath damLake Ackerman1979actionsstorage reservoir damupstreamNerlerk Embankment1979actionsstorage reservoir damupstreamMiber Road1979actionsstorage reservoir damvarious directionsmassMiber Road1979action lakelayer beneath damactionslayerDucan DamN/Aaction lakelayerlayerlayerDucan DamN/Aaction lakelayerlayerlayerBreference [†] :1. Hazen and Metcalf (1918), Hazen (1986),	13b		1978				downstream	mass			×	
La Marquesa Dam - U/S Slope 1985 Der I data only gently sloping ground downslope mass La Marquesa Dam - U/S Slope 1985 storage reservoir dam upstream layer beneath dam La Marquesa Dam - D/S Slope 1985 storage reservoir dam upstream layer beneath dam storage reservoir dam upstream layer beneath dam N/A Marcus Dam N/A zone (1918), Hazen (1918), 2. Seed (1969), 3. US Army Corps of Eng. (1930), Casagrande (1965), Middlebrooks (1940), Marcusen & Krinitzsky (1976); 1. Hazen and Metcalf (1918), Hazen (1983), Lucia (1981), Lucia et al. (1983), Marcus & Krinitzsky (1976); 1. Bennett (1986), 5. Ross (1968); 5. Ross (1970), Lucia (1981), Lucia (1982), Marcus & & Krinitzsky (1976); 1. Bennett (1986), Janita (1986), Janita (1988), Metchers & Sladen (1992), Gu (1992), Gu (1982), Andrus & Youd (1983), 1. Store & tal. (1979), Isihiata (1988), River et al. (1988), Metchers & & Sladen (1992), Gu (1982), Andrus & Youd (1980), 1. Store & Atal (1988), I. B. Hyvicw et al. (1988), Rober of Pass), Poner et al. (1986), Andrus & Youd (1980), 1. Store & Atal (1988), I. B. Hyvicw et al. (1988), Poner et al. (1985), Poner et al. (1986), Dept. of Water Resources (1980), 1. Store & Atal (1988), I. B. Hyvicw et al. (1988), Poner et al. (1985), Poner et al. (1985), Dept. of Water Resources (198	14		2001			tailings dam	downstream	mass				
La Marquesa Dami - U/S Slope 1985 storage reservoir dam upstream layer beneath dam La Marquesa Dam 1985 storage reservoir dam upstream layer beneath dam La Paima Dam 1987 storage reservoir dam upstream layer beneath dam Lake Ackernan 1987 storage reservoir dam upstream layer beneath dam Lake Ackernan 1987 storage reservoir dam upstream layer beneath dam Nerlerk Embankment 1979 storage reservoir dam upstream layer beneath dam NA 1979 subsea hydraulic fill load downslope layer N/A NA N/A zoned earthfill hydroelectric dam no failure N/A Reference*tores*t I. Hazen and Metcalf (1918), Hazen (1969), Lucia (1981), Lucia et al. (1982), Casagrande (1965), Middlebrooks (1940), Marcusen & Krimitzsky (1976); Reference*tores*tores*torestore and Metcalf (1918), Fazen (1966), Lucia (1981), Lucia et al. (1982), Seed (1976), Lucia (1981), Lucia et al. (1982), Seed (1976), Lucia (1981), Lucia et al. (1982), Seed (1976), Lucia (1981), Lucia et al. (1982), Seed et al. (1976), Middlebrooks (1940), Marcusen & Krimitzsky (1976); Reference*tores*tores*tore at al. (1970), Isinhara (1986), Seed (1976), Lucia (1981), Lucia (1981), Lucia et al. (1982), Gu (1992), Gu (1992),	1 4	I a Marcusco Dom 11/0 Clan	2001	BPI data only		gently sloping ground	downslope	mass				
La Palma Dam - U/S stope 1985 storage reservoir dam downstream layer beneath dam La Palma Dam 1985 CPT data only storage reservoir dam upstream layer beneath dam Lake Ackerman 1983 CPT data only storage reservoir dam upstream layer beneath dam Nerlerk Embankment 1983 CPT data only subsea hydraulic fill berm various directions mass gently sloping ground downslope layer no failure N/A Duncan Dam N/A zoned earthfill hydroelectric dam no failure N/A which is founded on sandy soil References [↑] : 1. Hazen and Metcalf (1918), Hazen (1918); 2. Seed (1969); 3. US Army Corps of Eng. (1939), Casagrande (1965), Middlebrooks (1940), Marcusen & Krinitzsky (1976); 4. Ross (1968); 6. Yamada (1966), [†] . 7. Yamada (1966), Lucia et al. (1932), Casagrande (1965), Middlebrooks (1981), Lucia et al. (1932); 10. Bennett (1989); 11. Seed et al. (1975), Seed et al. (1988), McRoberts & Sladen (1992); Gu (1992); 12. Lee et al. (1981), Lucia et al. (1983), Gu (1992); Gu (1992); 13. Lee et al. (1981), Lucia et al. (1983), Marcusen et al. (1976); Berti et al. (1983), Marcusen et al. (1979), Ishihara (1984), Baziar & Doby (1995); 14. Harder (1988), Mores et al. (1090), Si Andrus & Youd (1987), Andrus & Youd (1989), 15, 16 & 17. De Alba et al. (1978), 18. Hyciw et al. (1990); 19. Sladen et al. (1985), Andrus & Youd (1987), Andrus & Youd (1989); 15, 16 & 17. De Alba et al. (1988), 18. Hyciw et al. (1990); 19. Sladen et al. (1080), Norder et al. (1982), Andrus & Youd (1983), Andrus & Youd (1982); 15, 16 & 17. De Alba et al. (1988), 18. Hyciw et al. (1990); 19. Sladen et al. (1090), Norder et al. (1982), Andrus & Youd (1983), Andrus & Andrus & Youd (1983),	14	La Maranana Dani - U/S Slope	C891			storage reservoir dam	upstream	layer beneath dam				
La Falma Dam 1985 storage reservoir dam upstream layer beneath dam 1987 hydraulic fill road embankment into lake layer beneath dam 1987 hydraulic fill road embankment into lake layer beneath dam 1979 1979 cPT data only subsea hydraulic fill berm various directions mass gently sloping ground downslope layer N/A zoned earthfill hydroelectric dam no failure N/A which is founded on sandy soil ayer N/A which is founded on sandy soil a failure N/A to failure N/A which is founded on sandy soil 1059; 5. Ross (1968); 6. Yamada (1966); 7. Yamada (1966), Lucia (1981), Lucia et al. (1952); 8. Ross et al. (1975), Seed (1979), Davis et al. (1988), McRoberts & Sladen (1992), Gu (1992); 12. Lee et al. (1981), Lucia et al. (1983), Dept. of Water Resources (1989); 15. le & 17. De Alba et al. (1979), 18. Hyciw et al. (1995); 1957), Roser et al. (1988), Monos et al. (1988), Monos et al. (1988), Nonos et al. (1988), Nonos et al. (1988), Nonos et al. (1992); 18. Hyciw et al. (1998), 1957), Roser et al. (1988), Nonos et al. (1988), Nonos et al. (1988), Monos et al. (1988), Monos et al. (1997), 18. Hyciw et al. (1997), 1953), 18. Hyciw et al. (1998), 18. Hyciw et al. (1998), 18. Hyciw et al. (1998), 1987), Roser et al. (1988), Nonos et al. (1988), Nonos et al. (1988), Nonos et al. (1998), Nonos et al. (1998), 18. Hyciw et al. (1998), 1987), Roser et al. (1988), Nonos et al. (1998), 18. Hyciw et al. (1998), 1987), Roser et al. (1988), Nonos et al. (1988), Roser et al. (1988), Nonos et al. (1988), Non	2 [La Marquesa Dam - D/S Slope	5861			storage reservoir dam	downstream	layer beneath dam				
Lake Ackerman1987hydraulic fill road embankmentinto lakelayerlayerNerlerk Embankment1983CPT data onlysubsea hydraulic fill bermvarious directionsmassXNerlerk Embankment197920000emthy sloping grounddownslopelayerXNerlerk Embankment197920000aenthfill hydroelectric damdownslopelayerXDuncan DamN/Azoned earthfill hydroelectric damno failureN/AXReferences [†] :1. Hazen and Metcalf (1918), Hazen (1918); 2. Seed (1969); 3. US Army Corps of Eng. (1939), Casagrande (1965), Middlebrooks (1940), Marcusen & Krinitzsky (1976);4. Ross (1968); 5. Ross (1968); 6. Yamada (1966); 7. Yamada (1966), Lucia (1981), Lucia et al. (1982); 8. Ross et al. (1969; 9. Mishima & Kimura (1981), Lucia et al. (1982);10. Bernett (1989); 11. Seed et al. (1975), Seed (1979), Davis et al. (1988), McRoberts & Sladen (1992); 6u (1992); 12. Lee et al. (1982), Lucia (1981), Lucia et al. (1988), McRoberts & Sladen (1992); 6u (1992); 12. Lee et al. (1987), Andrus & Youd (1989), Stortes et al. (1988), Poners et al. (1988), Youde et al. (1988), Morease et al. (1988), Row of et al. (1988), Row of et al. (1988), Morease et al. (1988), Bariar & Dobry (1995); 13. Harder (1988), Row of et al. (1988), Andrus & Youd (1987), Andrus & Youd (1989);15. 16 & 17. De Alba et al. (1988), 18. Hyrciw et al. (1990); 19. Staden et al. (1988), Roese et al. (1987), Room of et al. (1988), Roese et al. (1987), Room of et al. (1988), Room of et	2	La Palma Dam	1985			storage reservoir dam	upstream	laver beneath dam				
 Nerlerk Embankment 1983 CPT data only subsea hydraulic fill berm various directions mass (1979) Heber Road 1979 CPT data only subsea hydroelectric dam various directions mass (1970), Marcusen & Krinitzsky (1976); N/A zoned earthfill hydroelectric dam of ailure N/A (1965), Middlebrooks (1940), Marcusen & Krinitzsky (1976); Reference⁷: 1. Hazen and Metcalf (1918), Hazen (1918); 2. Seed (1969); 3. US Army Corps of Eng. (1939), Casagrande (1965), Middlebrooks (1940), Marcusen & Krinitzsky (1976); Reference⁷: 1. Hazen and Metcalf (1918), Hazen (1918); 2. Seed (1969); 3. US Army Corps of Eng. (1932); 8. Ross et al. (1965), Middlebrooks (1940), Marcusen & Krinitzsky (1976); Ross (1968); 5. Ross (1968); 6. Yamada (1966); Lucia (1981), Lucia et al. (1982); 8. Ross et al. (1972), Gu (1970), Lucia (1981), Lucia et al. (1982); 8. Ross et al. (1972), Gu (1970), Lucia (1981), Lucia et al. (1983), McRoberts & Sladen (1992), Gu (1992); 11. Seed et al. (1979), Davis et al. (1988), Youd et al. (1982), Andrus & Youd (1987), Andrus & Youd (1987), Andrus & Youd (1987), Andrus & Youd (1989), 11. Seed et al. (1978), Baziar & Dobry (1995); 11. Harder (1988), Youd et al. (1983), Andrus & Youd (1987), Andrus & Youd (1987), Andrus & Youd (1989), 11. Seed et al. (1978), Baziar & Dobry (1995); 14. Harder (1988), Youd et al. (1983), Andrus & Youd (1987), Andrus & Youd (1987), Andrus & Youd (1989), 11. Seed et al. (1978), Baziar & Dobry (1995); 14. Harder (1988), Youd et al. (1985), Andrus & Youd (1987), Andrus & Youd (1987), Andrus & Youd (1989), 11. Seed et al. (1990); 19. Sladen et al. (1988), Roevee et al. (1988), Intervent et al. (1988), 18. Hryciw et al. (1990); 19. Sladen et al. (1988), Roevee et al. (1988), Roevee et al. (1988), 1000), Sladen et al. (1988), 1000), Sladen et al. (1988), 1000), Sladen et al. (1988), Roevee et al. (1988), 1000), Sladen et al. (1988), 1000), Sladen et al. (1988), 1000), Sladen et al. (1988), Roevee et al. (1988), Roevee et al. (1998), 1000), Slade	× ·	Lake Ackerman	1987			hydraulic fill road embankment	into lake	laver				
 Heber Road 1979 Bently sloping ground downslope layer N/A zoned earthfill hydroelectric dam no failure N/A which is founded on sandy soil References⁺: 1. Hazen and Metcalf (1918), Hazen (1918); 2. Seed (1969); 3. US Army Corps of Eng. (1939), Casagrande (1965), Middlebrooks (1940), Marcusen & Krinitzsky (1976); 4. Ross (1968); 5. Ross (1968); 6. Yamada (1966), Lucia (1981), Lucia et al. (1982); 8. Ross et al. (1969; 9. Mishima & Kimura (1970), Lucia (1981), Lucia et al. (1982), Bennett (1989); 11. Seed et al. (1975), Seed et al. (1988), McRoberts & Sladen (1992), Gu (1992); 12. Lee et al. (1985), Dept. of Water Resources (1989); 15. 16 & 17. De Alba et al. (1978), 18. Hryciw et al. (1990); 19. Sladen et al. (1988), Nonces et al. (1000), Sladen & Murus & Youd (1987), Andrus & Youd (1989); 	19	Nerlerk Embankment	1983	CPT data only		subsea hydraulic fill berm	various directions	mass			~	>
Duncan Dam N/A 2 References [†] : 1. Hazen and Metcalf (1918), Hazen (1918); 2. Seed (1969); 3 4. Ross (1968); 5. Ross (1968); 6. Yamada (1966) [‡] , 7. Yamada (1966), Luci 10. Bennett (1989); 11. Seed et al. (1975), Seed (1979), Davis et al. (1988), 13a&b. Marcusen et al. (1979), Ishihara (1984), Baziar & Dobry (1995); 14, 15, 16 & 17. De Alba et al. (1988), 18. Hryciw et al. (1990): 19. Sladen et al	20	Heber Road	1979			gently sloping ground	downslone	laver			<	<
References [†] : 1. Hazen and Metcalf (1918), Hazen (1918); 2. Seed (1969); 4. Ross (1968); 5. Ross (1968); 6. Yamada (1966) [‡] , 7. Yamada (1966), Luci 10. Bennett (1989); 11. Seed et al. (1975), Seed (1979), Davis et al. (1988), 13a&b. Marcusen et al. (1979), Ishihara (1984), Baziar & Dobry (1995); 14. 15, 16 & 17. De Alba et al. (1988), 18. Hryciw et al. (1990): 19. Sladen et al.	21	Duncan Dam	N/A			zoned earthfill hydroelectric dam	no failure	N/A				
References [†] : 1. Hazen and Metcalf (1918), Hazen (1918); 2. Seed (1969); 4. Ross (1968); 5. Ross (1968); 6. Yamada (1966) [‡] , 7. Yamada (1966), Luci 10. Bennett (1989); 11. Seed et al. (1975), Seed (1979), Davis et al. (1988), 13a&b. Marcusen et al. (1979), Ishihara (1984), Baziar & Dobry (1995); 14. 15, 16 & 17. De Alba et al. (1988), 18. Hryciw et al. (1990); 19. Sladen et al						which is founded on sandy soil		A 7 1 4 7				
		References [†] : 1. Hazen and Metc 4. Ross (1968); 5. Ross (1968); 6. 10. Bennett (1989); 11. Seed et al. 13a&b. Marcusen et al. (1979), 1sl 15, 16 & 17. De Alba et al. (1988)	alf (1918), 1 Yamada (1 (1975), Set hihara (1982	Hazen (1918); 2. S 966) [‡] ; 7. Yamada ed (1979), Davis e 1), Baziar & Dobry v et al (1990), 10	ieed (1969) (1966), Lu t al. (1988), / (1995); 14	; 3. US Army Corps of Eng. (1939) cia (1981), Lucia et al. (1982); 8. R Seed et al. (1988), McRoberts & S I. Harder (1988), Youd et al. (1985) 1. 1086-0, 1087), Paccord et al. (1985)), Casagrande (1965), N toss et al. (1969; 9. Mii Sladen (1992), Gu (1996),), Andrus et al. (1986),	(1940), shima & Kimura (197 2); 12. Lee et al. (197 Andrus & Youd (197	Marcusen & 0), Lucia (19 85), Dept. of 87), Andrus (: Krinitzsky (981), Lucia e Water Resou & Youd (198	(1976); tt al. (1982); urces (1989); 89);	

* The SPT data were from two boreholes through natural soil; however, the failure appears to be due to failure of the underwater fill in which no SPT data are available ⁺ In addition to the three main references: Seed (1987), Seed and Harder (1990), Stark and Mesri (1992)

[‡] Yamada (1966) did not specifically discuss the Kawagishi-Cho Building; however, it did refer to the Niigata Railway Station which was founded on piles and did not fail during the EQ and mentioned that "neighboring buildings without pile foundation[s] suffered severe unequal settlement or tipping"

Table 3. Additional key facts for each of the case histories

Table 4. $(N_1)_{60}$ values selected by various authors for each of the case histories

Cas	se History	Researchers	(N1)60	FC	Comments
No.	Name		In-situ	Clean sand equivalent	· · · /	
1	Calaveras Dam	Seed (1987)		12		Typical value for hydraulic sand fill in original structure, based on "tests performed in recent years"
	* No SPTs performed	Seed & Harder (1990)		12		Adopted value by Seed (1987)
		Stark & Mesri (1992)		12		Adopted value by Seed (1987)
		Poulos (1988)		7	> 60	Adopted N ₁ =2; assuming ER=60% & FC>60%, gives $(N_1)_{60}$ -cs = 7
2	Sheffield Dam	Seed (1969)				Estimated Dr of 35 to 40% for upper 1 to 1.5 fet of foundation material, based on degree of compaction of about 76%
	* No SPTs performed	Seed (1987)		6 to 8		Based on estimated D_r of 40 to 50%; appears to use correlations such as in Skempton (1986)
		Seed & Harder (1990)		6		
3	Fort Peck Dam	Stark & Mesri (1992) Marcusen &	≥ 7	6	· ·····	Dr of 40 to 50% in shell material and 55% in foundation sands
	* Limited SPTs performed	<u>Krinitzsky (1976)</u> Seed (1987)	·····	11 to 12		Based on foundation sands having a Dr of 45 to 50%, based on Marcusen &
		Poulos (1988)		7.3	30	Krinitzsky (1976)
4	Solfatara Canal Dike	Ross (1968)				Adopted N ₁ =5.3; assuming ER=60% & FC=30%, gives $(N_1)_{60}$ -cs =7.3 Noted that original north levee could be considered to have had a similar D ₁ t
	* No SPTs performed	Seed (1987)		5		the existing south levee, which was estimated from borings to be about 32%
	in a roputomed	5000 (1987)		5		Based on a relative density of 30% and the fact that the sand is clean uniform fine sand
_		Poulos (1988)	·····	0	<5	Adopted N ₁ =0 ($D_r \approx 32\%$); assuming ER=60% & FC<5%, gives (N ₁) ₆₀ -cs = 0
5	Lake Merced Bank	Ross (1968)				Range in raw N (based on BH1 and BH2 combined): 4 to 21 (average 11) in unit B, 8 to 24 (average 16) in unit C
		Seed (1987)		5	· · · · · · · · · · · · · · · · · · ·	Estimated D _r of 40%
		Seed & Harder (1990)		6		
		Stark & Mesri (1992)		6	3	
		This study	7**			Two boreholes: BH1 (located outside failure zone); BH2 (located within slic area). Unit B average raw N is 4 to 21 (avg. 16) in BH1 and 4 to 10 (avg. 7) in BH2; BH2 results in $(N_1)_{60}$ in-situ = 7. ** However, BH1 was located well outside fill, through natural soil; BH2 was located on the outside edge of the cut/fill boundary of the highway, through natural soils. It appears that the soil that played the predominant role in the failure was underwater fi SPT results in natural soil have no meaning for the fill; therefore, remove cas
6	Kawagishi-Cho Building	Seed (1987)			······	history from the database.
		This study				not less than 4 (referring to paper by Yamada, 1966) A value of 4 is probably reasonable: low blowcounts of raw N = 2 to 4.5 wer
:	* SPTs reported by Yamada (1966) were performed at a nearby building only					recorded in the upper sand layer beneath the Railway Station (Yamada, 1966) it appears that the ground conditions beneath the Kawagishi-Cho building were assumed to be similar (probably a good assumption, based on an SPT sounding for Kawagishi-Cho site presented by Ishihara & Koga, 1981)
	Uetsu Railway	Seed (1987)		< 3		"since the embankment had performed satisfactorily under train loadings
	Embankment					before the earthquake, it [was] unlikely that the [equivalent clean sand] $(N_1)_{60}$ value for the sand was less than about 3"
:	* No SPTs performed	Seed & Harder (1990)		3		
0	Snow River Bridge Fill	Stark & Mesri (1992)		3		
ο.	C	Ross et al. (1969)				Raw N of 5 to 10 in upper 40 to 50 ft of river bed and increasing to 30 at tips of deepest piles (\approx 60 feet)
		Seed (1987)		. 7		Value given in Seed (1987) text (Noted that the soil involved in the lateral slide was a gravelly sand)
7 Uet Em * N 8 Snc		0 10 tr 1 (1000)		5		Value given in Seed (1987) table
		Seed & Harder (1990) Stark & Mesri (1992)	F	7	10 -	
9 H		Stark & Mesri (1992) Seed (1987)	5	7 to 10	10 to 30	
				3 to 4		Seed (1987) felt that the $(N_1)_{60}$ -cs "is not likely to be less than about 3 or 4 in a railway embankment of this type" since the embankment had performed satisfactorily under loadings prior to the earthquake, similar to the Uetsu Railway Embankment
*		Seed & Harder (1990)		3		
10 0		Stark & Mesri (1992)		3		
10 5	San Fernando Juvenile Hall	Seed (1987) Davis et al. (1988)	2 4	6	50 to 75	For the saturated sandy silt in unit B1
	-				50 to 75	Augusta 20
		Seed & Harder (1990)	<u>.7 to 11.2</u> 6*	10		Average value = 7.9 * Note: it appears that the value of $(N_1)_{60}$ -cs reported by Seed & Harder (1990) has been double corrected for fines content since the value they assumed as the in-situ $(N_1)_{60}$ was 6; however, this was the equivalent clean
		Stark & Mesri (1992)	6*	10.5 to 13.0		sand value reported by Seed (1987), having already been corrected for fines content from the in-situ (N_1) ₆₀ of 2

11 Lower San Fernando Dam	Seed (1987)				Based on a post-EQ average $(N_1)_{60}$ in D/S shell of about 16 and D _r of about 5 to 55%; assumed pre-EQ values would be lower; selected $(N_1)_{60}$ cs of 15 based
* Post-EQ SPTs in downstream shell only	Seed et al. (1988)	11.5	13.5	25 to 30	on D _r of 50%) Pre-EQ (N ₁) ₆₀ in-situ in U/S shell estimated from average (N ₁) ₆₀ in-situ of 14.5 in D/S shell (post-EQ), corrected to 12.5 downstream (pre-EQ), corrected to 11.5 upstream (pre-EQ)
	Poulos (1988)			50	Final correction to (N1)60cs of 13.5 based on FC of 25 to 30%
	100003 (1900)			30	Adopted N_1 =8.5; assuming ER=60% and FC=50%; no indication as to if this was for U/S or D/S side
	Davis et al. (1988)	5.5*	7.5 to 9.5*	50	Assigned an $(N_1)_{60}$ of 8.5 to the downstream side of the dam * Note: if $(N_1)_{60}$ of 8.5 is assumed to be the in-situ $(N_1)_{60}$ in the D/S site, it becomes an U/S, pre-EQ $(N_1)_{60}$ in situ of 5.5, using the $\Delta(N_1)_{60}$ values applied by Seed et al. (1988); this converts to an $(N_1)_{60}$ -cs of 9.5 for FC = 50%; however, for FC = 25 to 30% (like Seed et al., 1988, assumed), $(N_1)_{60}$ cs = 7.5
	Seed & Harder (1990)		13.5		
	Stark & Mesri (1992)	11.5	13.5 to 17.5	25 to 30	Clean sand equivalent value depends on type of correction factor used
	McRoberts & Sladen (1992)		4		Based on a sensible lower bound for the post-EQ D/S in-situ $(N_1)_{60}$ of 8, converted to a pre-EQ U/S $(N_1)_{60}$ -cs of 7 Based on CPT logs from 1985 fieldwork (GEI Consultants, 1988), giving a lower bound post-EQ D/S tip resistance of 24 bars (25 tsf) and converting to a
	· · · · · · · · · · · · · · · · · · ·				post-EQ D/S $(N_1)_{60}$ cs of 7 or a pre-EQ U/S $(N_1)_{60}$ cs of 4
12 Upper San Fernando Dam	Dept. of Water Resources (1989)	13	15	25	Based on average post-earthquake $(N_1)_{60}$ in-situ of 17.5 in lower elevations of the hydraulic fill, corrected to pre-earthquake average $(N_1)_{60}$ of 13, corrected to pre-earthquake average $(N_1)_{60}$ cs of 15 for FC = 25% (N.B. correction from post-earthquake to pre-earthquake of 4.5 blows based on estimated relative density change of 12%)
	Seed & Harder (1990)		15	25	,
	Stark & Mesri (1992)	13	15 to 19	25	Clean sand equivalent value depends on type of correction factor used
13 Mochi-Koshi Tailings13a – Dam 2	Ishihara (1984)			85	In tailings pond, raw N of 0 down to 15 m, at which raw $N = 3$ to 7; in starter dikes (did not fail), raw N about 5
	Seed (1987)	1	6		
	Poulos (1988) Davis et al. (1988)	0		> 60	
	Seed & Harder (1990)		5	> 60 80	
	Stark & Mesri (1990)	0	5 5 to 7	80	Clean cond convivolant value days 1
13b- Dam 1	This study	0	5	00	Clean sand equivalent value depends on type of correction factor used Assumed same values as for Dam 2 (Seed & Harder, 1990)
14 Whiskey Springs Fan	Harder (1988)	8	10	20	Based on Becker Penetration Test (BPT) values converted to equivalent SPT values; total fines content = 20%
* No SPTs performed;	Seed & Harder (1990)	8	11	40	40% FC based on sand matrix alone
BPTs were converted to SPT values	Stark & Mesri (1992)	8	11 to 15	40	Clean sand equivalent value depends on type of correction factor used
15 Le Marco D	Andrus & Youd (1989)	6 to 12			Average CPT results converted to equivalent SPT values
15 La Marquesa Dam- U/S Slope	De Alba et al. (1988)	4*	6	30	* Note, however, that only two blowcounts were measured in the silty sand layer that liquefied
	Seed & Harder (1990) Stark & Mesri (1992)	4	6 6 to 10		01
16 La Marquesa Dam	De Alba et al. (1988)	<u>4</u> 9*	11	20	Clean sand equivalent value depends on type of correction factor used
- D/S Slope	Seed & Harder (1988)	9	11	20	* Only three blowcounts in layer that liquefied; 9 = highest value
•	Stark & Mesri (1992)	9	11 to 14		Clean sand equivalent value depends on type of correction factor used
	This study	5.5	7.5	20	Lower bound approach
17 La Palma Dam	De Alba et al. (1988)	3	4	15	* In the damaged area, the only blowcounts measured in the loose silty sand layer were one blowcount in each of two boreholes located midslope.
	Seed & Harder (1990)	3	4		
19 Laka Ashar	Stark & Mesri (1992)	3	4 to 7	15	Clean sand equivalent value depends on type of correction factor used
18 Lake Ackerman	Hryciw et al. (1990)	3			$(N_1)_{60}$ in-situ: 6 to 8 (failed section); 1 to 4 in (unfailed section)
19 Nerlerk Embankment	Stark & Mesri (1992)	3	4	0 to 5	
* No SPTs performed	Jefferies et al. (1990) Stark & Mesri (1992)	10 to 11	11 10 to 12.5	0 to 10	Inferred from CPT results Referred to Jefferies et al. (1990); Clean sand equivalent value depends on
20 Heber Road	Youd & Bennett (1983)				type of correction factor used Raw N of 1 to 7 (safety hammer) or 2 to 4 (donut hammer)
	Davis et al. (1988)	1.4		15	Based on raw N of Lower a doubt - 5 (+ 11 C
	Stark & Mesri (1992)	1.4	1.5 to 5	15	Based on raw N of 1 over a depth of 6 to 11 feet Clean sand equivalent value obtained depends on type of correction factor used
21 Duncan Dam	Plewes et al. (1994) and Pillai & Stewart	10 to 18.5			N_1_{60} values increased with depth in soil unit of interest (see Table 5)

	History	Researchers	Su	Comments
No.	Name	_	(psf)	
1	Calaveras Dam	Seed (1987)	750	Decad on part failure of the contraction of the
		Poulos (1988)	730	Based on post-failure configuration of slide mass; no specific details are given
		100003 (1988)	700	Incorporated effects of energy and dynamics of failure; calculated 1500 psf for pre-failure
				driving stress, 250 psf for post-failure driving stress, and 600 psf to 1100 psf for mobilized
		Davis et al. (1988)	700	undrained shear strength; 700 psf is recommended value Same results as Poulos (1988)
		Seed and Harder (1990)	650 ± 50	No explanation given errors to service of the state of th
		Seed and Harder (1990)	050 ± 50	No explanation given; appears to represent range from the minimum value of 600 psf to recommended value of 700 psf, given by Poulos (1988)
		Stark and Mesri (1990)	650 ± 50	recommended value of 700 psi, given by Poulos (1988)
2	Sheffield Dam	Seed (1987)	50	Decod on a simple with the
~	Shernela Dun	Seed (1987)	50	Based on a simple calculation assuming the entire base liquefied and acted as slip surface
		Seed and Harder	75 ± 25	with thrust leading to failure a result of the 15 ft deep upstream reservoir No explanation
		Stark and Mesri	75 ± 25 76 ± 25	No explanation
3	Fort Peck Dam	Lucia (1981), Lucia et al. (1982)	250	
5	Fort Feek Dam	Seed (1987)	600	Based on post-failure configuration of the slide mass
		Seed (1987)	600	No specific explanations; stated that "other studies indicate a pre-sliding driving stress of
		Deulas (1088)	700	about 700 psf; a reasonably conservative value [for Su] is 600 psf"
		Poulos (1988)	700	Incorporated effects of energy and dynamics of failure; calculated 1800 psf for pre-failure
				driving stress, 50 psf for post-failure driving stress, and 500 psf to 1100 psf for mobilized
		D (1000)		undrained shear strength; 700 psf is recommended value
		Davis et al. (1988)	700	
		Seed & Harder (1990)	350 ± 100	
	0.10	Stark & Mesri (1992)	351 ± 100	······································
4	Solfatara Canal Dike	Seed (1987)	130	"the average shear stress at the base of the dike"; no further details given
		Poulos (1988)		Incorporated effects of energy and dynamics of failure; calculated 105 psf for pre-failure
				driving stress, 0 psf for post-failure driving stress; no specific value was calculated for the
				mobilized undrained shear strength, but concluded it would have to be greater than 0 psf
		Seed & Harder (1990)	50 ± 25	No explanation
		Stark & Mesri (1992)	51 ± 25	No explanation
5	Lake Merced Bank	Seed (1987)	100	No explanation
		Seed & Harder (1990)	100	
		Stark & Mesri (1992)	100	
6	Kawagishi-Cho Building	Seed (1987)	120	Value calculated as the average shear stress in the foundation, based on an estimated
	5		120	average base pressure from the building of 600 psf; thus, it appears that S_u was calculated
				using the plasticity theory undrained foundation failure equation of $q_f = 5.14 S_u$, where q_f
				is the base pressure from the building
		Seed & Harder (1990)	120	
		Stark & Mesri (1992)	120	
7	Uetsu Railway	Lucia (1981), Lucia et al. (1982)		Decidence of City of City in
'	Embankment	Seed (1987)	35	Based on post-failure configuration of the slide mass
	Embankment	Seed & Harder (1990)	35	Adopted the value from the work of Lucia (1981), Lucia et al. (1982)
			40	No explanation
		Stark & Mesri (1992)	40	
		This study	37.5 ± 2.5	Based on reported range of 35 to 40 psf; however, value would be larger if energy effects
				had been taken into account, as done by Poulos (1988) and Davis et al. (1988) for some of
0		0 1 (1007)		the case histories
8	Snow River Bridge Fill	Seed (1987)	50	Concluded that "the residual strength of the liquefied sand was very low, probably about
				50 psf, for movements of about 10 ft to have occurred"; no other explanation given, but
		C 10.11 1 (1000)		possibly something like a Newmark sliding block analysis was used
		Seed & Harder (1990)	50	· · · · · · · · · · · · · · · · · · ·
		Stark & Mesri (1992)	50	
9	Koda Numa Embankment	Lucia (1981), Lucia et al. (1982)	25	Based on post-failure configuration of slide mass which flowed over level ground
		Seed (1987)	25	Value in Seed (1987) text (referring to the work by Lucia (1981), Lucia et al. (1982))
			50	Value in Seed (1987) table
		Seed & Harder (1990)	50	
		Stark & Mesri (1992)	50	
10	San Fernando Juvenile Hall		140	Noumark type deformation or about for a second seco
	sui i emando suvenne man	Seca (1967)	140	Newmark-type deformation analysis for a maximum ground surface acceleration of 0.6g and the 5 ft observed surface displacements
		Davis et al. (1988)	200	and the 5 h observed stillage displacements
		Davis et al. (1988)	200	Incorporated effects of energy and dynamics of failure, using a Newmark-type analysis,
				calculated 55 psf for both the pre- and post-failure driving stresses and a mobilized undrained shear strength of 50 to 450 psf with reserve lating the stresses and a mobilized
		Seed & Harder (1990)	120 1 70	undrained shear strength of 50 to 450 psf with recommendation to use an S _u of 200 psf
			$\frac{130 \pm 70}{121 \pm 70}$	No explanation given; upper end coincides with recommendation by Davis et al. (1988)
11	Lower Cor France L. D.	Stark & Mesri (1992)	$\frac{131 \pm 70}{750}$	
11	Lower San Fernando Dam	Seed (1987)	750	Estimated based on the pre-failure slope configuration and assigning know strengths to the
		<u> </u>		non-liquefied zones at the toe and crest of the slope
		Seed et al. (1988)	580	35-percentile strength of 850 psf (the pre-EQ U/S Su estimated by steady-state analysis)
				(N.B. reported that "actual residual shear strength determined from configuration when
				slide mass stopped moving" was 400 ± 100 psf; lower bound of this range calculated
				"knowing that sliding would stop when the factor of safety attained a value of unity" and
				"based on the configuration of the slide mass at the end of sliding"; upper bound calculated
				by allowing for "the inertia effects associated with the rate of movement and a possible 70% reduction in strength of the liquefied soil as it moves into the reservoir")
				(1)W(reduction in stress of City 1) City 1 (City 1)

Table 5. S_u values selected by various authors for each of the case histories

		Davis et al. (1988)		Incorporated effects of energy and dynamics of failure; calculated 950 psf for pre-failure
		Poulos (1988)	750	driving stress and 510 psf for mobilized undrained shear strength Incorporated effects of energy and dynamics of failure; calculated 1000 psf for pre-failure driving stress, and 500 to 1000 psf for mobilized undrained shear strength; 750 psf is recommended value
		Seed & Harder (1990)	400 ± 100	
		Stark & Mesri (1992)	401 ± 100	Subid on mangs of Seed et al. (1988)
		Gu (1992)		Finite element post-earthquake deformation analyses, based on collapse mechanics and ultimate state strengths, investigating stress redistribution; found that the observed progressive failure wold be predicted if the ultimate state strength in the hydraulic fill were lower than the average value based on laboratory tests reported by Seed et al. (1988)
12	Upper San Fernando Dam	Dept. of Water Resources (1989)	500 to 700	Liquefied zone (Zone IV) predicted to have occurred in bottom half of hydraulic fill, based on earthquake-induced compressive strain potential analysis; S_u values calculated based on FS=1 for a circular failure surface through the pre-failure dam configuration and assuming strength parameters for the other, non-liquefied zones (range in S_u values based on range in strength parameters assigned to the partially liquefied zone around Zone IV)
		Seed & Harder (1990)	600 ± 100	b particular parameters designed to the partially inductied zone around zone iv)
	······	Stark & Mesri (1992)	601 ± 100	
13	Mochi-Koshi Tailings	Lucia (1981), Lucia et al. (1982)	210	Based on post-failure configuration of the tailings remaining in the tailings pond
	13a - Dam 2	Seed (1987)	210	Value in Seed (1987) test (Referred to work by Lucia (1981), Lucia et al. (1982))
			250	Value in Seed (1987) table
		Poulos (1988)		Incorporated effects of energy and dynamics of failure; calculated 390 psf for pre-failure driving stress, 100 psf for post-failure driving stress, and 75 to 200 psf for mobilized undrained shear strength; 130 psf is recommended value
		Davis et al. (1988)	250	
		Seed & Harder (1990)	250 ± 150	
	101	Stark & Mesri (1992)	250 ± 150	
	13b - Dam 1	Poulos (1988)	60	Incorporated effects of and dynamics of failure; calculated 540 psf for pre-failure driving stress, < 50 psf for post-failure driving stress, and 50 to 110 psf for mobilized undrained shear strength; 60 psf is recommended value
		Davis et al. (1988)	60	
14	Whiskey Springs Fan	Harder (1988)	130 to 160	Lower bound estimated using a stability analysis under static loading conditions and determining S _u for FS=1; upper bound estimated using 1978 Makdisi-Seed modification or Newmark's sliding block double integration method, based on 1.2 m of movement
		Seed & Harder (1990)	150 ± 10	Referred to Harder (1988), but used a slightly narrower range
		Stark & Mesri (1992)	150 ± 10	
15	La Marquesa Dam - U/S Slope	De Alba et al. (1988)	76 to 340	Lower bound estimated based on the post-failure configuration and equals the post-failure driving stress; upper bound based on the initial configuration of the slope, including horizontal stresses from the core plus inertia effects
		Seed & Harder (1990)	200 ± 120	
		Stark & Mesri (1992)	200 ± 120	
16	La Marquesa Dam - D/S Slope	De Alba et al. (1988)	266 to 580	Lower bound estimated based on the post-failure configuration and equals the post-failure driving stress; upper bound based on the initial configuration of the slope, including horizontal stresses from the core plus inertia effects
		Seed & Harder (1990)	400 ± 150	
17	L-D-1 D	Stark & Mesri (1992)	400 ± 150	
17	La Palma Dam	De Alba et al. (1988)		Lower bound estimated based on the post-failure configuration and equals the post-failure driving stress. Upper bound based on the initial configuration of the slope, including horizontal stresses from the core plus inertia effects
		Seed & Harder (1990)	200 ± 100	
1.0	F _1 _ A 1	Stark & Mesri (1992)	200 ± 100	
18	Lake Ackerman	Hryciw et al. (1990)	170 to 260	Both strengths estimated using 2-D stability analyses, one in failed zone (giving S_u = 260 psf) and one in the zone that did not fail, although seismic trucks had passed over it (giving S_u = 170 psf); analysis assumed a single S_u throughout both the loose sand fill and the denser sand above the groundwater table; therefore, S_u may be overpredicted
19	Nerlerk Embankment	Sladen et al. (1985a)	< 42 psf	For all slides in Nerlerk embankment; represents steady state strength required for limiting equilibrium of an infinite slope, based on the ranges in post-failure slope angles and thicknesses of the failed soil masses (did not take into account dynamics of the failure, as done by Poulos (1988) and Davis et al. (1988) for other cases)
		Jefferies et al. (1990)		S_u/σ'_{vo} = approximately 0.15 ($K_o = 0.7$)
		Stark & Mesri (1992)		$S_u \sigma v_0$ approximately 0.15 ($R_0 = 0.1$) $S_u \sigma' v_0 = 0.148$, based on Jefferies et al. (1990); based on average embankment height of 12 m and estimated unit weight of soil of about 18 kN/m ³ , this strength ratio translates into an average S_u of approximately 14.4 kPa (300 psf)
20	Heber Road	Davis et al. (1988)	100 psf	Incorporated effects of energy and the dynamics of the lateral spread, using a Newmark type analysis to match observed movements; results indicated both pre- and post-failure driving stresses of 40 psf and mobilized S_u of 100 psf
		Stark & Mesri (1992)	100 psf	
21		Pillai & Salgado (1994)		$S_u/\sigma'_{vo} = 0.21$, based on laboratory testing on undisturbed frozen samples (based on post-cyclic undrained monotonic simple shear test results)

C	ז <mark>ע</mark> '	$S_{u} = 0.21\sigma_{v}'$	Su	$(N_1)_{60}$
(kPa)	(psf)	(kPa)	(psf)	in-situ
100	2089	21	439	10
200	4177	42	877	10
300	6266	63	1316	12.4
400	8354	84	1754	13.2
600	12531	126	2632	14.5
800	16708	168	3509	15.7
1000	20886	210	4386	17.3
1200	25063	252	5263	18.5

Table 6. Duncan Dam results (Byrne et al., 1994)

Note: $S_u = 0.21\sigma'_v$ is based on undrained monotonic direct simple shear testing of undisturbed samples

05/06/98 Version

n analysis
10
Summary of deformat
1.
Table

	Case History	VUIIUUI	Introduced	I USU AIIZIC	brittleness index	0	g' _{vi}	Approx.
No.	Name	Height	Strain	Pre angle	$I_B = \overline{tan\beta_i} - \overline{tan\beta_f}$	(Stark & N	(Stark & Mesri, 1992)	RSR
		(m/m)	(%)		$\tan \beta_i$	(Jsd)	(kPa)	(p'_i/p'_{us})
	Calaveras Dam	3.0	99.8	0.31	0.70	2855	136.7	1.8
2	Sheffield Dam	3.9	157.9			1975	94.6	10.5
ς	Fort Peck Dam	7.5	186.8	0.20	0.80	10815	517.8	12.4
4	Solfatara Canal Dike	11.0	558.1	0.13	0.88	955	45.7	7.6
S	Lake Merced Bank	1.8	123.9	0.71	0.34	950	45.5	3.8
9	Kawagishi-Cho Building					1225	58.7	4.1
1	Uetsu Railway Embankment	11.5	637.5	0.14	0.87	2690	128.8	26.9
8	Snow River Bridge Fill	1.0	2.2	1.00	0.00	2100	100.5	16.8
6	Koda Numa Embankment	6.0	346.4	0.13	0.88	1550	74.2	12.4
10	San Fernando Juvenile Hall	0.0	0.1	1.00	0.00	1940	92.9	6.0
11	Lower San Fernando Dam	1.4	56.7	0.37	0.64	3930	188.2	3.9
12	Upper San Fernando Dam	0.1	3.4	1.00	0.00	2975	142.4	2.0
13a	Mochi-Koshi Tailings -Dam 2	12.0	439.1	0.22	0.78	2715	130.0	4.3
13b	-Dam 1	16.7	609.9	0.22	0.78	4072.5	195.0	
14	Whiskey Springs Fan	0.1	1.2	1.00	0.00	2630	125.9	7.0
15	La Marquesa Dam - U/S Slope	1.4	70.9	0.46	0.56	1600	76.6	3.2
16	La Marquesa Dam - D/S Slope	0.9	62.6	0.53	0.52	1790	85.7	1.8
17	La Palma Dam	0.5	30.7	0.50	0.55	1670	80.0	3.3
18	Lake Ackerman	1.9	93.9	0.28	0.74	1845	88.3	1
19	Nerlerk Embankment	4.2	93.5	0.12	0.88	1	ł	!
20	Heber Road	ł	1	;	;	800	38.3	1
21	Duncan Dam	N/A	N/A	N/A	N/A	1	-	

Note: Horizontal strain = observed runout divided by initial slope length, where initial slope length = horizontal distance from the toe of the initial slope to the point immediately below the crest of the initial slope (i.e. calculated from initial slope height and angle).

42

05/06/98 Version

Table 8. Summary of range in data reported by various authors

Case History				Sa						$(N_1)_{60}$	(N ₁) ₆₀ in-situ		FC	
No. Name	Min	Minimum	Maximum	mum	Avg. of Max/Min	fax/Min	+/- for Max/Min	fax/Min	Minimum Ma	Maximum	Avg. of	+/- for	Minimum Maximum	Maximum
	(Jsd)	(kPa)	(Jsd)	(kPa)	(Jsd)	(kPa)	(psf)	(kPa)			Max/Min	Max/Min	(%)	(%)
1 Calaveras Dam	009	28.7	750	35.9	675	37 3	75	у к	ć	٢	Y V	vc		097
2 Sheffield Dam	50	۲ ر	001	9 4	21	2.00	36	, c	4 -	- \) ı r	C.4		00
2 Fort Deal Dom	0.50	r 9 5	001	0, t, C		0.0	C7 5	1.2	4	٥	0 [°]	-		25*
	007	12.0	/00/	53.5	475	22.7	225	10.8	5.3	10	7.65	2.35		30
4 Solfatara Canal Dike	0	0.0	130	6.2	65	3.1	65	3.1	0	4	2	7		Ş
5 Lake Merced Bank	100	4.8	100	4.8	100	4.8	0	0.0	5	7	9	-	ŝ	m
6 Kawagishi-Cho Building	120	5.7	120	5.7	120	5.7	0	0.0	4	4	4	0		
7 Uetsu Railway Embankment	35	1.7	40	1.9	38	1.8	б	0.1	m	ŝ	ŝ	C		
8 Snow River Bridge Fill	50	2.4	50	2.4	50	2.4	0	0.0	S	5.5	5.25	0.25		
9 Koda Numa Embankment	25	1.2	50	2.4	38	1.8	13	0.6	б	4	3.5	0.5		
10 San Fernando Juvenile Hall	60	2.9	200	9.6	130	6.2	70	3.4	2	9	4	2	50	65
11 Lower San Fernando Dam	300	14.4	750	35.9	525	25.1	225	10.8	5.5	11.5	8.5	Ś	25	25
	500	23.9	700	33.5	600	28.7	100	4.8	13	13	13	0	25	>60
Mochi-Koshi Tailings	100	4.8	400	19.2	250	12.0	150	7.2	0	-	0.5	0.5	>60	80
~	50	0.0	110	0.0	80	3.8	30	1.4	0	1	0.5	0.5	>60	80
14 Whiskey Springs Fan	130	6.2	160	7.7	145	6.9	15	0.7	9	12	6	ę	40	40
15 La Marquesa Dam - U/S Slope	76	3.6	340	16.3	208	10.0	132	6.3	4	4	4	0	30	30
16 La Marquesa Dam - D/S Slope	266	12.7	580	27.8	423	20.3	157	7.5	6	6	6	0	20	20
17 La Palma Dam	100	4.8	300	14.4	200	9.6	100	4.8	ŝ	б	ę	0	15	15
18 Lake Ackerman	170	8.1	260	12.4	215	10.3	45	2.2	ŝ	ę	ŝ	0	C	v
19 Nerlerk Embankment	42	2.0	300	14.4	171	8.2	129	6.2	10	11	10.5	0.5	, c	. 2
20 Heber Road	100	4.8	100	4.8	100	4.8	0	0.0	-	-		0	ì	29
 estimated for this study 														

43

Table 9. Summary of minimum (N1)60 approach

	Case History	Type of	s	Su	E)	(N ₁) ₆₀	FC	Comments
No.	Name	Failure	mean	an	in-situ (clean sand	(%)	
		-	(Jsd)	(kPa)		equivalent		
-	Calaveras Dam	flow	700	33.5	0	7	>60	Minimum N, and S. from Poulos (1988) assumed N.=N.) (i.e. ER=60%)
7	Sheffield Dam	flow	75	3.6	4	9	25^{\dagger}	1 [sed hower stated D = 35% and (N.). (D 2 =48 for clean cond environment of for in view
ς	Fort Peck Dam	flow	700	33.5	Ś	-	30	S from Davie et al (1988). N. from Davies (1989) assumed N $-N$) i i $\sim ED - EOV$
4	Solfatara Canal Dike	flow	50	2.4	0	. 0	\$ \$	ου ποιτι τάταιο σται. (1700), κη ποιπτι συπος (1700), αδαμητεύ Ιντ−(181) ₆₀ (1.ε. ΕΚ−0076) N. from Poullos (1988): assumed N.=(N.)(i.e. ΕΡ=60%)
5	Lake Merced Bank	slump	100	4.8	5	2	ŝ	Case record validity doubtful; no data from fill in lake, data from natural ground behind failure zone
9	Kawagishi-Cho Building	building foundation	120	5.7	4	4	CS‡	Case record is different from all other cases because it was not a slope
7	Uetsu Railway Embankment	flow	80	3.8	б	ы	CS [‡]	Original S _u based on runout; doubled to account for energy effects
8	Snow River Bridge Fill	lateral spread	50	2,4	5	6.5	15 [†]	3
6	Koda Numa Embankment	flow	50	2.4	ŝ	ŝ	CS⁺	
10	San Fernando Juvenile Hall	lateral spread	200	9.6	7	9	65	S,, from Davis et al. (1988); original Seed (1987) (N.).,=2: Seed & Harder (1990) annified AN ravies
11	Lower San Fernando Dam	flow/slump	500	23.9	9	8	25	(N ₁) ₆₀ from lower bound assessment of sandy SPTs in GEI (1988) and S. from Davis et al. (1988)
12	Upper San Fernando Dam	slump	600	28.7	5.5	7.5	25	Department of Water Resources (1989) Figure 432 data corrected to nre-event
13a	Mochi-Koshi Tailings -Dam 2	flow	130	6.2	0	5	80	S _u from Davis et al. (1988) and Poulos (1988); (N ₁) _{so} from Ishihara (1984)
13b	-Dam 1	flow	60	0.0	0	5	80	As above
14	Whiskey Springs Fan	lateral spread	150	7.2	5	8	40	(N,) _{so} from Andrus and Youd (1989) from Becker equivalents
15	La Marquesa Dam - U/S Slope	slump	200	9.6	4	9	30	
- 16	La Marquesa Dam - D/S Slope	slump	400	19.2	5.5	7.5	20	
17	La Palma Dam	slump	200	9.6	3	4	15	
18	Lake Ackerman	flow/slump	215	10.3	ŝ	т	0	
19	Nerlerk Embankment	flow	315	15.1	б	4	10	Lower bound $(N_1)_{A_1}$ based on Sladen et al. (1985) CPT data and $n_1(N_1)_{n=0}$ 5
20	Heber Road	lateral spread	100	4.8	1	3	29	Spread for soil A2 also in Seed et al. (1985) trigger database: see Fear & McRoherts (1993, 1995)
[†] estim	estimated for this study; \ddagger assumed to be clean sand (CS)	clean sand (CS)						

44



Figure 1. Relationship between clean sand equivalent SPT blowcount, (N1)60-cs, and undrained residual strength (Su) from case histories (after Seed and Harder, 1990).



Case histories from Seed and Harder (1990) and Stark and Mesri (1992) plotted in terms of relative runout (runout/initial height) and slope angle ratio (ratio of post-failure slope angle to initial slope angle). Figure 2.



Figure 3. Case histories from Seed and Harder (1990) and Stark and Mesri (1992) plotted in terms of brittleness index versus approximate RSR, with the relationship suggested by Sladen et al. (1985b) shown for comparison.



Figure 4. Pre-failure and post-failure cross-sections for examples of different types of failures: (a) flow: Calaveras Dam (1), after Hazen (1918); (b) lateral spread: Whiskey Springs Fan (14), after Harder (1988); (c) slump: La Marquesa Dam Upstream and Downstream (15 and 16), after De Alba et al. (1988).



(1990) and Stark and Mesri (1992) classified as flow failures, with theoretical clean Ottawa sand line (after Fear and Plot of S_u versus clean sand equivalent SPT blowcount, (N₁)₆₀-cs, for those case histories from Seed and Harder Robertson, 1995) and Duncan Dam (21) results shown for comparison. Figure 5.



Figure 6. Plot of S_u versus minimum clean sand equivalent SPT blowcount, (N₁)₆₀-cs, for those case histories classified as flow failures, with Seed and Harder (1990) lines and theoretical clean Ottawa sand line (after Fear and Robertson, 1995) shown for comparison; note: S_u and (N₁)₆₀-cs are the revised values from this study (see Table 9).



Figure 7. Plot of S_u versus minimum clean sand equivalent SPT blowcount, (N₁)₆₀-cs, for all case histories except Lake Merced (5), with Seed and Harder (1990) lines and theoretical clean Ottawa sand line (after Fear and Robertson, 1995) shown for comparison; note: S_u and (N₁)₆₀-cs are the revised values from this study (see Table 9).



case histories except Lake Merced (5), with Stark & Mesri (1992) lines and clean sand Ottawa line (after Fear and Plot of undrained strength ratio, S_{u/O'vi}, versus minimum clean sand equivalent SPT blowcount, (N₁)₆₀-cs, for all Robertson, 1995) shown for comparison; note: S_u and (N₁)₆₀-cs are the revised values from this study (see Table 9), while values of σ'_{vi} are from Stark and Mesri (1992) (see Table 7). Figure 8.

List of Figure Captions

- Figure 1. Relationship between clean sand equivalent SPT blowcount, $(N_1)_{60}$ -cs, and undrained residual strength (S_u) from case histories (after Seed and Harder, 1990).
- Figure 2. Case histories from Seed and Harder (1990) and Stark and Mesri (1992) plotted in terms of relative runout (runout/initial height) and slope angle ratio (ratio of post-failure slope angle to initial slope angle).
- Figure 3. Case histories from Seed and Harder (1990) and Stark and Mesri (1992) plotted in terms of brittleness index versus approximate RSR, with the relationship suggested by Sladen et al. (1985b) shown for comparison.
- Figure 4. Pre-failure and post-failure cross-sections for examples of different types of failures: (a) flow: Calaveras Dam (1), after Hazen (1918); (b) lateral spread: Whiskey Springs Fan (14), after Harder (1988); (c) slump: La Marquesa Dam Upstream and Downstream (15 and 16), after De Alba et al. (1988).
- Figure 5. Plot of S_u versus clean sand equivalent SPT blowcount, (N₁)₆₀-cs, for those case histories from Seed and Harder (1990) and Stark and Mesri (1992) classified as flow failures, with theoretical clean Ottawa sand line (after Fear and Robertson, 1995) and Duncan Dam (21) results shown for comparison.
- Figure 6. Plot of S_u versus minimum clean sand equivalent SPT blowcount, (N₁)₆₀-cs, for those case histories classified as flow failures, with Seed and Harder (1990) lines and theoretical clean Ottawa sand line (after Fear and Robertson, 1995) shown for comparison; note: S_u and (N₁)₆₀-cs are the revised values from this study (see Table 9).
- Figure 7. Plot of S_u versus minimum clean sand equivalent SPT blowcount, (N₁)₆₀-cs, for all case histories except Lake Merced (5), with Seed and Harder (1990) lines and theoretical clean Ottawa sand line (after Fear and Robertson, 1995) shown for comparison; note: S_u and (N₁)₆₀-cs are the revised values from this study (see Table 9).
- Figure 8. Plot of undrained strength ratio, S_{u/}σ'_{vi}, versus minimum clean sand equivalent SPT blowcount, (N₁)₆₀-cs, for all case histories except Lake Merced (5), with Stark & Mesri (1992) lines and clean sand Ottawa line (after Fear and Robertson, 1995) shown for comparison; note: S_u and (N₁)₆₀-cs are the revised values from this study (see Table 9), while values of σ'_{vi} are from Stark and Mesri (1992) (see Table 7).